

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG23001717/ANY3E2
Date: 21/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800125794
Claimant Vehicle No :	SJK6322E	Insured Vehicle No :	EY3733H
Date of Loss:	14/02/2023	Nature of Claim:	TP
		Claim No:	6910289823SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK6322E	Engine No:	F2004024B48B20A
Make & Model:	BMW 318I, 2.0 (A)	Chassis No:	WBA70DY0008C28799
Reg. Date:	15/12/2021 (Man. Year: 2021)	Odometer:	21352 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,522.61	6,973.86	9,548.75	57.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,400.00	2,480.00	63.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,402.61	8,373.86	12,028.75	58.96
Approved Total (Overridden) (S\$)		6,700.00		
Nett Amount (S\$)	20,402.61	6,700.00	13,702.61	67.16

INSPECTION

Date of Assignment:	15/02/2023	JDM AUTOCARE (HQ)
Date Inspected:	21/02/2023 Inspected At:	1 KAKI BUKIT AVENUE 6 #01-51, Autobay @ Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
2	2		*REAR BUMPER SIDE RETAINER - L/R	Not Necessary	202.55 FL	*- FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	46.45 FL	*- FL
4	1		*REAR BUMPER REFLECTOR - LH	Not Necessary	65.80 FL	*- FL
5	1		*REAR BUMPER REFLECTOR GARNISH - LH	Cut	105.60 FL	*105.60 FL
6	1		*REAR BUMPER REFLECTOR - RH	Cracked	65.80 FL	*65.80 FL
7	1		*REAR BUMPER REFLECTOR GARNISH - RH	Not Necessary	105.60 FL	*- FL
8	1		*REAR BUMPER REFORCEMENT	Dented	715.25 FL	*715.25 FL
9	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	960.75 FL	*480.00 FL
10	1		*REAR BUMPER REVERSE SENSOR WIRE	Not Necessary	398.15 FL	*- FL
11	1		*REAR BUMPER CENTRE ATTACHMENT	Cracked	241.30 FL	*241.30 FL
12	1		*REAR BUMPER OPENER SWITCH	Not Necessary	195.10 FL	*- FL
13	1		*REAR BUMPER BOOT ANTENNA	Not Necessary	260.80 FL	*- FL
14	1		*REAR BUMPER OPENER CONTROL MODULE	Damaged	780.00 FL	*380.00 FL
15	1		*REAR BUMPER OPENER SENSOR HOLDER	Necessary	180.60 FL	*180.60 FL
16	1		*REAR BUMPER LOWER DUST COVER (CENTRE)	Not Necessary	175.40 FL	*- FL
17	1		*TAIL LAMP ASSY - LH	Not Necessary	750.60 FL	*- FL
18	1		*TAIL LAMP ASSY - RH	Not Necessary	750.60 FL	*- FL
19	1		*TAILLAMP SEALANT	Not Necessary	100.00 FL	*- FL
20	1		*TAILLAMP CLIPS	Not Necessary	28.00 FL	*- FL
21	1		*REAR END PANEL	Repair	586.45 FL	*- FL
22	1		*REAR END PANEL TOP TRIM	Not Necessary	119.50 FL	*- FL
23	1		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	50.00 FL	*- FL
24	1		*BOOTLID	Dented	1,580.30 FL	*1,580.30 FL
25	1		*BOOTLID WEATHER STRIPE	Not Necessary	169.10 FL	*- FL
26	1		*BOOTLID BADGE	Necessary	75.00 FL	*75.00 FL
27	1		*BOOTLID BADGE CLIPS	Necessary	6.00 FL	*6.00 FL
28	1		*BOOTLID LAMP - LH	Not Necessary	552.80 FL	*- FL
29	1		*BOOTLID LAMP - RH	Not Necessary	552.80 FL	*- FL
30	1		*BOOTLID OUTER KEYLESS ANTENNA	Not Necessary	362.10 FL	*- FL
31	1		*REAR EXHAUST SILENCER	Not Necessary	1,127.85 FL	*- FL
32	1		*EXHAUST SILENCER HOOK	Not Necessary	79.60 FL	*- FL
33	1		*EXHAUST SILENCER BRACKET	Not Necessary	68.15 FL	*- FL
34	1		*EXHAUST SILENCER HEATER SHIELD - CENTER	Not Necessary	116.85 FL	*- FL
35	1		*REAR BUMPER FASCIA -M SPORT	Deformed	2,500.00 FS	*1,700.00 FS
36	1		*REAR BUMPER DIFFUSER CENTER - M SPORT	Deformed	2,000.00 FS	*1,800.00 FS
37	1		*EXHAUST SILENCER CHROME PIPE	Not Necessary	480.00 FS	*- FS
38	1		*REAR BUMPER SIDE AIR VENT COVER	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,104.85	7,359.85
- List Item Discount on L Items 5.00/10.00% (\$\$)	582.24	385.99
Total Parts (\$\$)	16,522.61	6,973.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TUFF COAT AFFECTED AREAS	New	180.00	30.00
2	TO RESET AND DECODE ELECTRONIC MODULE SYSTEM	New	500.00	120.00
3	TO RESPRAY AFFECTED AREAS	New	1,500.00	600.00
4	TO REMOVE & REPLACE DAMAGED PARTS, REPAIR BOOT LID COVER AND ALIGNED ALL PARTS	New	1,200.00	600.00
5	TO REMOVE & REFIT EXHAUST SILENCER	New	300.00	0.00
6	TO REMOVE & REFIT INTERIOR UPHOLSTERY	New	200.00	50.00
Gross Labour Cost (\$)			3,880.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >