

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23001729/ANY3E2**Date:** 18/04/2023REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No :

SND8366E

Insured Vehicle No :

SKX3007E

Date of Loss: 11/02/2023

Nature of Claim:

TP

Claim No:

DMPC2300102H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SND8366E**

Make & Model: BYD E6H, (A)

Engine No: 0

Reg. Date: 26/01/2022 (Man. Year: 2021)

Chassis No: LC0CE4DC0M0057899

Colour: Blue

Odometer: 0 km

Engine Capacity: 0 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,970.02	16,394.20	16,575.82	50.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,820.00	2,850.00	1,970.00	40.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,790.02	19,244.20	18,545.82	49.08
Approved Total (Overridden) (S\$)		15,300.00		
Nett Amount (S\$)	37,790.02	15,300.00	22,490.02	59.51

INSPECTION

Date of Assignment: 15/02/2023

Date Inspected: 16/02/2023

Inspected At:

V.z Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #02-02
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	M1-MPV	BYD E6H (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND8366E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,062.40 FL	*1,410.00 FL
2	1		*FRONT BUMPER RETAINER LH	Not Necessary	79.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Not Necessary	79.00 FL	*- FL
4	1		*FRONT BUMPER BRACKET LH	Not Necessary	79.00 FL	*- FL
5	1		*FRONT BUMPER BRACKET RH	Not Necessary	79.00 FL	*- FL
6	1		*FRONT BUMPER GRILLE	Not Necessary	958.00 FL	*- FL
7	1		*FRONT BUMPER GRILLE CHROME	Cut	385.00 FL	*385.00 FL
8	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	275.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GARNISH LH	Not Necessary	285.00 FL	*- FL
10	1		*FRONT BUMPER LOWER GARNISH RH	Not Necessary	285.00 FL	*- FL
11	1		*FRONT BUMPER LOGO	Necessary	227.00 FL	*227.00 FL
12	1		*FRONT REINFORCEMENT	Dented	668.00 FL	*580.00 FL
13	1		*FRONT SUPPORT PANEL	Not Necessary	785.00 FL	*- FL
14	1		*HEADLAMP LH	Not Necessary	3,250.00 FL	*- FL
15	1		*HEADLAMP BRACKET LH	Not Necessary	785.00 FL	*- FL
16	1		*HEADLAMP RH	Cracked	3,250.00 FL	*2,800.00 FL
17	1		*HEADLAMP BRACKET RH	Not Necessary	785.00 FL	*- FL
18	1		*REAR BUMPER TOP	Distorted	1,405.00 FL	*1,405.00 FL
19	1		*REAR BUMPER BOTTOM	Distorted	1,380.00 FL	*745.00 FL
20	1		*REAR BUMPER RETAINER LH	Not Necessary	87.00 FL	*- FL
21	1		*REAR BUMPER RETAINER RH	Not Necessary	87.00 FL	*- FL
22	1		*REAR BUMPER BRACKET LH	Not Necessary	87.00 FL	*- FL
23	1		*REAR BUMPER BRACKET RH	Not Necessary	87.00 FL	*- FL
24	1		*REAR REFLECTOR LH	Not Necessary	198.00 FL	*- FL
25	1		*REAR REFLECTOR RH	Not Necessary	198.00 FL	*- FL
26	1		*REAR REFLECTOR CENTRE	Cracked	425.00 FL	*425.00 FL
27	1		*REAR BUMPER LOWER GARNISH	Cracked	769.00 FL	*480.00 FL
28	1		*REAR BUMPER INNER BRACKET LH	Dented	259.00 FL	*259.00 FL
29	1		*REAR BUMPER INNER BRACKET RH	Dented	259.00 FL	*259.00 FL
30	1		*REAR END PANEL	Distorted	852.00 FL	*852.00 FL
31	1		*REAR END PANEL REINFORCEMENT	Distorted	565.00 FL	*565.00 FL
32	1		*TAILGATE	Dented	5,459.40 FL	*4,561.00 FL
33	1		*TAILGATE LOCK	Damaged	578.00 FL	*578.00 FL
34	1		*TAILGATE WEATHERSTRIP	Cut	373.00 FL	*373.00 FL
35	2		*TAILGATE HINGE	Not Necessary	176.00 FL	*- FL
36	1		*TAILGATE LAMP LH	Not Necessary	458.00 FL	*- FL
37	1		*TAILGATE LAMP RH	Not Necessary	458.00 FL	*- FL
38	1		*TAILGATE LOGO	Necessary	108.00 FL	*108.00 FL
39	1		*TAILGATE EMBLEM BYD E6	Necessary	108.00 FL	*108.00 FL
40	1		*TAILGATE EMBLEM BYD MOTORSPORTS	Necessary	108.00 FL	*108.00 FL
41	1		*TAILGATE CHROME MOULDINGS	Not Necessary	345.00 FL	*- FL
42	1		*TAILLAMP LH	Cracked	783.00 FL	*605.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*TAILLAMP RH	Cracked	783.00 FL	*605.00 FL
44	1		*TAILLAMP BRACKET LH	Not Necessary	275.00 FL	*- FL
45	1		*TAILLAMP BRACKET RH	Not Necessary	275.00 FL	*- FL
46	1		*TAILLAMP CHROME MOULDING LH	Not Necessary	175.00 FL	*- FL
47	1		*TAILLAMP CHROME MOULDING RH	Not Necessary	175.00 FL	*- FL
48	1		*THIRD BRAKE LAMP	Not Necessary	327.00 FL	*- FL
49	1		*WINDSCREEN	Not Necessary	857.00 FL	*- FL
50	1		*WINDSCREEN MOULDING	Not Necessary	472.00 FL	*- FL
51	1		*WIPER	Not Necessary	135.00 FL	*- FL
52	1		*WIPER MOTOR	Not Necessary	575.00 FL	*- FL
53	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
54	1		*REAR NUMBER PLATE W/GARNISH	Dented	90.00 FS	*60.00 FS
55	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
56	1		*REAR NUMBER PLATE W/GARNISH	Deformed	90.00 FS	*60.00 FS
57	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
59	1		*REVERSE SENSOR	Damaged	480.00 FS	*350.00 FS
60	1		*REVERSE SENSOR HOLDER	Necessary	80.00 FS	*80.00 FS
61	1		*JOINT SEALANT	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,467.80	18,138.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,497.78	1,743.80
Total Parts (\$\$)	32,970.02	16,394.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	New	200.00	100.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	60.00
3	REMOVE AND REFIT FRONT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	New	150.00	0.00
4	REMOVE AND REFIT REAR ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	New	150.00	80.00
5	PANEL BEATING ON FRONT ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	New	800.00	300.00
6	PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,200.00	1,000.00
7	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	800.00	250.00
8	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	1,200.00	1,000.00
9	APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (\$\$)			4,820.00	2,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >