

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG23001732/AQY3M4**Date:** 20/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100499798
<b>Claimant Vehicle No :</b>	SMR3436H	<b>Insured Vehicle No :</b>	SGX1288X
Date of Loss:	02/02/2023	Nature of Claim:	TP
		Claim No:	8011894805SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMR3436H</b>		
Make & Model:	MAZDA CX-5, 2.0 STANDARD PLUS 2WD I2 (A)	Engine No:	PE31406969
Reg. Date:	30/12/2019 (Man. Year: 2019)	Chassis No:	JM6KF2W7AK0337368
Colour:	Red	Odometer:	18850 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,770.80	1,331.60	439.20	24.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	490.00	570.00	53.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,830.80</b>	<b>1,821.60</b>	<b>1,009.20</b>	<b>35.65</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,450.00</b>		
<b>Nett Amount (\$\$)</b>	<b>2,830.80</b>	<b>1,450.00</b>	<b>1,380.80</b>	<b>48.78</b>

INSPECTION

Date of Assignment:	15/02/2023		JDM AUTOCARE
Date Inspected:	16/02/2023	Inspected At:	1 KAKI BUKIT AVENUE 6, #01-51, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883
Estimated Period of Repair:	2.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	1,664.50 FL	*1,664.50 FL
2	1		*REAR DOOR LH LOCK	Not Necessary	325.00 FL	*- FL
3	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	224.00 FL	*- FL
					<b>Sub Total (S\$)</b>	<b>2,213.50</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>442.70</b>
					<b>Total Parts (S\$)</b>	<b>1,770.80</b>
						<b>1,331.60</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	400.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	300.00	200.00
3	TUFF COAT	New	50.00	0.00
4	WIRING CHECK	New	50.00	30.00
5	TRANSFER REAR DOOR LH	New	80.00	60.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,060.00</b>	<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >