

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1766G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	SCRATCHED / BROKEN	503.04	503.04
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR BUMPER LOWER COVER	SCRATCHED	654.96	654.96
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	378.32	-
1	BACK DOOR GARNISH ASSY	BROKEN	1,054.71	1,054.71
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	62.14	62.14
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	62.14	62.14
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-684.33	-584.25
			2,052.98	1,752.74
	SPECIAL NETT ITEMS			
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (SN)	NECESSARY	60.00	60.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			285.70	150.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID.		400.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,060.00	880.00
	GRAND TOTAL		3,398.68	2,782.74





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,200.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC23001739/Sqp3e2

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser