



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2625Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR END '50KM/H' STICKER (SN)	NECESSARY	10.00	10.00
1	REAR (CENTRE) RED TAPE (SN)	NECESSARY	15.00	15.00
1	REAR END MAIN CHASSIS GUARD (9MM) (SN)	BADLY DENTED	2,500.00	1,500.00
1	REAR O/S MAIN CHASSIS FRAME (SN)	TO REPAIR SEE LABOUR	1,000.00	-
			3,525.00	1,525.00
	<b><u>LABOUR</u></b>			
	REMOVE THE NECESSARY AFFECTED PARTS, CUT / WELD REAR END MAIN CHASSIS GUARD, STRAIGHTEN REAR O/S MAIN CHASSIS FRAME, REAR O/S CORNER LOCK AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF REAR O/S MAIN CHASSIS FRAME.		2,000.00	900.00
	SPRAYPAINT (INCLUDE UNDER COATING).		800.00	400.00
	CHECK ELECTRICAL.		50.00	40.00
			2,850.00	1,340.00
<b>GRAND TOTAL</b>			<b>6,375.00</b>	<b>2,865.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,865.00</b>

Report Ref No. CS3/LIP22011033/Dqy3e2-1

MARKET VALUE: \$125,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,407.00=NETT VALUE: \$115,593.00

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.