4/3/23, 8:41 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI23001743/SQY3Q2

03/04/2023 Date:

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle

GBK3665E

Insured Vehicle No:

YP5910K

Date of Loss:

No:

14/02/2023

Nature of Claim:

ΤP

Claim No: CDMFG23000368

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK3665E**

NISSAN NV200, 1.5 (M) K9KE628D695121 Make & Model: Engine No: Reg. Date: 18/06/2020 (Man. Year: 2019) Chassis No: VSKYBAM20U0179347

> White Odometer: 80955 km

Engine Capacity: Market Value/New Car

Price:

Colour:

N/A

Sum Insured (S\$): Market Value/New Car Price

1461 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 175/70 R14 Rear Tyre Size: Front Left Side: KAPSEN 5 mm Rear Left Side: Bridgestone 5 mm Rear Right Side: Front Right Side: KAPSEN 5 mm Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,017.62	396.90	1,620.72	80.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	800.00	300.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) 3,117.62	1,196.90	1,920.72	61.61
Approved Total (Overridden) (S\$)	950.00		
(1	S\$) 3,117.62	950.00	2,167.62	69.53
+ GST 8.00/8.00% (S\$) 249.41	76.00	173.41	69.53
Nett Amount (S\$) 3,367.03	1,026.00	2,341.03	69.53

INSPECTION

Date of Assignment: 15/02/2023

AB ENGINEERING PTE LTD (HQ)

Date Inspected: 16/02/2023 Inspected At: 25 SENANG CRESCENT, SINGAPORE 416598

Singapore 416598

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/3/23, 8:41 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 Apr 2023)

Parts: N/A NISSAN NV200 1.5 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBK3665E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	887.70 FL	*- FL
2	1		*FRONT GRILLE	Scratched	356.10 FL	*356.10 FL
3	1		*FRONT EMBLEM NISSAN	Scratched	84.90 FL	*84.90 FL
4	1		*HEADLAMP LOWERED GARNISH -LH	Repair	331.60 FL	*- FL
5	1		*FRONT BUMPER	Repair	541.50 FL	*- FL
6	4		*FRONT BUMPER CLIPS	Not Necessary	40.00 FL	*- FL
F=Fra	F=Franchise part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)			2,241.80 224.18	441.00 44.10	
				Total Parts (S\$)	2,017.62	396.90
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE AND REPLACE OF THE ACCIDENT DAMAGED PARTS .TO HEAT /WELD ,CUT -OFF THE FRONT BONNET ,FRONT GRILLE ,HEADLAMP LOWERED GARNISH LH ,FRONT BUMPER ,ETC INCLUDING KNOCKING REPAIR ,RESHAPE AND ADJUST OF SAME	New	600.00	400.00
2	TO PUTTY AND SPRAY PAINTING ON ACCIDENT PANELS ,FRONT BONNET, HEADLAMP LOWERED GARNISH LH ,ETC INCLUDING KNOCKING ,REPAIR ,RESHAPE AND ADJUST OF SAME	New	500.00	400.00
	Gross Labour	Cost (S\$)	1,100.00	800.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >