

AB ENGINEERING PTE LTD

Co. Reg No: 202117273R

10 KAKI BUKIT ROAD 2 #01-25, FIRST EAST CENTRE, SINGAPORE 417868

Tel : 8858 6282

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Report No: SA1X232E0001_14-02-2

Date: 16/2/2023

Signature: [Signature]

Date: 16/2/2023

Type: COMMERCIAL

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: GBK3665E

Chassis No: VSKYBAM20U0179347

Engine No: K9KE628D695121

MAKE: NISSAN

MODEL : NV200 ACENTA 1.5 DCI MANUAL

Replacement of Damaged Parts

S/No.	Description	Qty	Our Recommendation
1	Front bonnet <i>dent R</i>	1	887.70
2	Front grille <i>scr</i>	1	356.10
3	Front emblem NISSAN <i>scr</i>	1	84.90
4	Headlamp lowered garnish - LH <i>scr R</i>	1	231.60
5	Front bumper <i>scr R</i>	1	541.50
6	Front bumper clips <i>LNN</i>	4	40.00

\$2,241.80

Less 10%

\$224.18

Total (P)

\$2,017.62

441

10% = 441

\$ 396.9

Labour Charges

- To dismantle and replace of the accident damaged parts; to heat/weld, cut-off the front bonnet, front grille, headlamp lowered garnish LH, front bumper, etc including knocking, repair, reshape and adjust of same.

\$600.00 400

- To putty and spray painting on accident panels, front bonnet, headlamp lowered garnish LH, etc including knocking, repair, reshape and adjust of same.

\$500.00 400

Total Labour: \$1,100.00

Final Repair Cost to Vehicle No : GBK3665E

Amount

Lump Sum Discount -20%

Total

Add GST 8%

Grand Total

1196.90

20% = 239.38

\$3,117.62

\$623.52

\$2,494.10

\$199.53

\$2,693.62

FT = 957.52

≈ 950