

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III23001745/KNY3E2**Date:** 12/06/2023**REFERENCE**Insured/Claimant: STARLAND CONSTRUCTION PTE LTD Policy No: D19MCV0001408_03
Date of Loss: 02/02/2023 Nature of Claim: OD Claim No: MCV2023D0001509**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBE8411U**
Make & Model: TOYOTA DYNA, 3.0 D (M) Engine No: 1KD2591398
Reg. Date: 31/03/2016 (Man. Year: 2016) Chassis No: KDY2318023621
Colour: Silver Odometer: 195129 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$50,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 195 R15X8 Rear Tyre Size: 165 R13X8 (D)
Front Left Side: Bridgestone 3 mm Rear Left Side: Triangle 5/5 mm
Front Right Side: Bridgestone 3 mm Rear Right Side: Triangle 5/5 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,544.00	3,504.00	1,040.00	22.89
Miscellaneous Items	11.88	11.88	0.00	0.00
Labour	3,750.00	1,670.00	2,080.00	55.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,305.88	5,185.88	3,120.00	37.56
Approved Total (Overridden) (S\$)		4,100.00		
- Excess (S\$)	0.00	3,100.00	-3,100.00	
(S\$)	8,305.88	1,000.00	7,305.88	87.96
+ GST 8.00/8.00% (S\$)	664.47	80.00	584.47	87.96
Nett Amount (S\$)	8,970.35	1,080.00	7,890.35	87.96

INSPECTIONDate of Assignment: 16/02/2023 Present Location: Kgc Workshop Pte Ltd (AMK)
Date Inspected: 16/02/2023 Inspected At: Kgc Workshop Pte Ltd (AMK)
14 Ang Mo Kio Street 63, Blk B
Singapore 569116
Estimated Period of Repair: 6.0 days**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Jun 2023)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE8411U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front center panel (WCP)	Bent	220.00 F	*380.00 F
2	1		*Front panel top rubber (WCP)	Dented	185.00 F	*185.00 F
3	1		*Front panel top garnish LHS (WCP)	Missing	75.00 F	*75.00 F
4	1		*Front grille (WCP)	Missing	255.00 F	*255.00 F
5	1		*Front grille Emblem (WCP)	Missing	40.00 F	*40.00 F
6	1		*Headlamp RHS (WCP)	Mtg Cracked	480.00 F	*480.00 F
7	1		*Headlamp LHS (WCP)	Mtg Cracked	480.00 F	*480.00 F
8	1		*Front Bumper (WCP)	Buckled	245.00 F	*245.00 F
9	1		*Aircon blower (WCP)	Mtg Cracked	385.00 F	*420.00 F
10	1		*front dashboard (WCP)	Serviceable	450.00 F	*- F
11	1		*Clutch set (WCP)	Serviceable	425.00 F	*- F
12	1		*Flywheel bearing (WCP)	Serviceable	15.00 F	*- F
13	1		*Top clutch pump (WCP)	Serviceable	110.00 F	*- F
14	1		*Low clutch pump (WCP)	Not Necessary	95.00 F	*- F
15	1		*Front Bumper clips	Necessary	50.00 FS	*50.00 FS
16	1		*front carplate	Serviceable	50.00 FS	*- FS
Supplementary #1						
17	1	87150-25060	*Radiator Heater Unit AIRCON HEATER UNIT INSTEAD OF RADIATOR HEATER UNIT(WCP)	Housing Cracked	580.00 F	*580.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,140.00	3,190.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	404.00	314.00
Total Parts (\$\$)	4,544.00	3,504.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.88	11.88
			Sub Total (\$)	11.88

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.	New	1,500.00	700.00
2	To putty and spray paint on all accident damage parts and other accident affected areas	New	1,200.00	650.00
3	Mechanic Labour to remove gearbox to repair and refit the same	New	550.00	0.00
4	Mechanic Labour To remove and refit dashboard	New	300.00	250.00
5	To check wiring system to facilitate repair and refit the same	New	120.00	20.00
Supplementary #1				
Labour Items				
6	top up aircon gas	New	80.00	50.00
			Gross Labour Cost (\$)	3,750.00
				1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >