

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Krishnan Bhuvaneshwari

Date: 01 Jun 2023

**Preliminary Advice**

Vehicle No	: GBE8411U	Accident Date	: 02/02/2023
Make	: TOYOTA DYNA	Policy No.	: D19MCV0001408_03
Assignment Date	: 16/02/2023	Excess	: S\$3,100.00
Date of Inspection	: 16/02/2023	Est. Duration of Repair	: 6
Inspection At	: KGC WORKSHOP PTE LTD (AMK) 14 ANG MO KIO STREET 63, BLK B SINGAPORE 569116		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,305.88 (inclusive supp \$718.00)
Revised Amount	:S\$	5,185.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,185.88
Lump Sum Repair	:S\$	4,100.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	5,236.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,764.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Kindly approve on supplementary.