

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Krishnan Bhuvanewari

Date: 16 Feb 2023

Preliminary Advice

Vehicle No	: GBE8411U	Accident Date	: 02/02/2023
Make	: TOYOTA DYNA	Policy No.	: D19MCV0001408
Assignment Date	: 16/02/2023	Excess	: S\$0.00
Date of Inspection	: 16/02/2023	Est. Duration of Repair	: 6
Inspection At	: KGC WORKSHOP PTE LTD (AMK) 14 ANG MO KIO STREET 63, BLK B SINGAPORE 569116		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,587.88
Revised Amount	:S\$	3,859.88
Check Items (Estimated)	:S\$	2,178.00
Total	:S\$	6,037.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	5,236.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,764.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.