

Kgc Workshop Pte Ltd (Co.Reg.No.201719986M)

14 Ang Mo Kio Street 63, Blk B

Singapore 569116

Tel: 64510353 /64536279 Fax: 64565140 Email:

joyce@kgcworkshop.com.sg;dj@kgcworkshop.com.sg;lincoln@kgcworkshop.com.sg;pohkin@kgcworkshop.com.sg

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D19MCV0001408	Date of Loss:	02/02/2023
Vehicle Reg. No.:	GBE8411U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	STARLAND CONSTRUCTION PTE LTD		
Make/Model:	TOYOTA DYNA, 3.0 D (M)	Vehicle Reg. Date:	31/03/2016
Vehicle Colour:	SILVER		
Engine No:	1KD2591398	Chassis No:	KDY2318023621
Odometer:	195129 KM		
Paint Type:			<i>NOT WITHIN</i>
Total Loss?	NO		<i>1 Rep @ 4100h</i>
Est. Duration of Repair (day)	<i>x 6 days</i>		<i>Meaning After Rain</i>
Present Location:	KGC WORKSHOP PTE LTD (AMK)		

COST OF CLAIMS	Amount
Parts	3,906.00
Miscellaneous Items	11.88
Labour	3,670.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,587.88
+ GST 8.00% (S\$)	607.03
Nett Amount (S\$)	8,194.91

This claim is handled by: CHONG POH KIN

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Feb 2023)
Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kgc Workshop Pte Ltd/GBE8411U/15/02/2023 15:23
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front center panel	0.00	0.00	By 380 *220.00 F ✓
2	1		*Front panel top rubber	2.1 0.00	0.00	*185.00 F ✓
3	1		*Front panel top garnish LHS	0.00	0.00	mit *75.00 F ✓
4	1		*Front grille	0.00	0.00	mit *255.00 F ✓
5	1		*Front grille Emblem	0.00	0.00	mit *40.00 F ✓
6	1		*Headlamp RHS	0.00	0.00	mg 480 *480.00 F ✓
7	1		*Headlamp LHS	0.00	0.00	480 *480.00 F ✓
8	1		*Front Bumper	0.00	0.00	Ben *245.00 F ✓
9	1		*Aircon blower	0.00	0.00	mg 420 *285.00 F ✓
10	1		*front dashboard	0.00	0.00	su *450.00 F X
11	1		*Clutch set	0.00	0.00	su *425.00 F Z
12	1		*Flywheel bearing	0.00	0.00	su *15.00 F Z
13	1		*Top clutch pump	0.00	0.00	su *110.00 F Z
14	1		*Low clutch pump	0.00	0.00	su *95.00 F X
15	1		*Front Bumper clips	0	0.00	su *50.00 FS ✓
16	1		*front carplate	0	0.00	su *50.00 FS X

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,560.00
+ Margin on L,N Items 10.00% (\$\$)	346.00
Total Parts (\$\$)	3,906.00

Kgc Workshop Pte Ltd/GBE8411U/15/02/2023 15:23. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.88
Sub Total (\$\$)			11.88

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.	New	700 1,500.00
2	To putty and spray paint on all accident damage parts and other accident affected areas	New	650 1,200.00
3	Mechanic Labour to remove gearbox to repair and refit the same	New	NN 550.00 X
4	Mechanic Labour To remove and refit dashboard	New	250 300.00
5	To check wiring system to facilitate repair and refit the same	New	200 120.00
Gross Labour Cost (\$\$)			3,670.00

Kgc Workshop Pte Ltd/GBE8411U/15/02/2023 15:23. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

repair parts, inclusive of replacement
 miscellaneous items
 To putty and spray paint

repair parts, inclusive of replacement
 miscellaneous items
 To putty and spray paint

repair parts, inclusive of replacement
 miscellaneous items
 To putty and spray paint

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 May 2023)
 Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: **Kgc Workshop Pte Ltd/GBE8411U/13/05/2023 15:20**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	87150-25060	*Radiator Heater Unit <i>Hausem</i>	0.00	0.00	*580.00 F ✓
			<i>Aircen</i>			
			Sub Total (\$)			580.00
			+ Margin on L,N Items 10.00% (\$)			58.00
			Total Parts (\$)			638.00 ✗

Kgc Workshop Pte Ltd/GBE8411U/13/05/2023 15:20. Not valid without Reference section
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	top up aircon gas	New	50.00 80.00
Gross Labour Cost (\$\$)			80.00



Kgc Workshop Pte Ltd/GBE8411U/13/05/2023 15:20. Not valid without Reference section
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >