

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III23001746/KWY3E2**Date:** 30/05/2023REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 26/10/2022

Nature of Claim: OD

Claim No: MFL2022D0008059

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMW9733J**

Make & Model: HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A) Engine No: G4FJLH805669

Reg. Date: 21/12/2020 (Man. Year: 2020)

Chassis No: KMHJ3812VLU390641

Colour: Metallic Black

Odometer: 20979 km

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$127,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,934.96	2,934.96	0.00	0.00
Miscellaneous Items	61.00	61.00	0.00	0.00
Labour	1,450.00	820.00	630.00	43.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,445.96	3,815.96	630.00	14.17
+ GST 8.00/8.00% (S\$)	355.68	305.28	50.40	14.17
Nett Amount (S\$)	4,801.64	4,121.24	680.40	14.17

INSPECTION

Date of Assignment: 16/02/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)

Date Inspected: 16/02/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	M1-SUV	HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW9733J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,617.80 FL	*1,617.80 FL
2	1		*FRONT BUMPER	Cracked	554.00 FL	*554.00 FL
3	1		*FRONT GRILLE	Cracked	1,087.00 FL	*1,087.00 FL
4	1		*FRONT BUMPER LOWER GARNISH	Dented	389.00 FL	*389.00 FL
5	1		*FRONT NUMBER PLATE GARNISH	Dented	20.90 FL	*20.90 FL
					Sub Total (S\$)	3,668.70
					- List Item Discount on L Items 20.00/20.00% (S\$)	733.74
					Total Parts (S\$)	2,934.96

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			61.00	61.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	800.00	400.00
2	To putty & respray on Front damage parts.	New	600.00	400.00
3	To check wiring & focus headlamp.	New	50.00	20.00
Gross Labour Cost (S\$)			1,450.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >