

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001753/UWP3Q2**Date:** 28/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00102782205
Claimant Vehicle No :	SMS5153E	Insured Vehicle No :	YP7391U
Date of Loss:	09/02/2023	Nature of Claim:	TP
		Claim No:	SNM23D201058/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS5153E	Engine No:	HR12129459K
Make & Model:	NISSAN SERENA, 1.2 Highway Star Premium E-Power (A)	Chassis No:	JN1EBAC27Z0000389
Reg. Date:	28/02/2020 (Man. Year: 2019)	Odometer:	60009 km
Colour:	Silver		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,509.21	1,509.21	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	170.00	450.00	72.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,129.21	1,679.21	450.00	21.13
+ GST 8.00/8.00% (S\$)	170.34	134.34	36.00	21.13
Nett Amount (S\$)	2,299.55	1,813.55	486.00	21.13

INSPECTION

Date of Assignment:	15/02/2023		
Date Inspected:	16/03/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	1.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2023)
Parts:	M1-MPV	NISSAN SERENA 1.2 Highway Star Premium E-Power (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS5153E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR MOTOR, GLASS LAMP ,CAMERA ASSY -RH	Cracked	1,564.40 FL	*1,564.40 FL
2	1		*SIDE MIRROR OUTER COVER (TOP-SPRAY)-RH	Cracked	112.50 FL	*112.50 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,676.90	1,676.90
- List Item Discount on L Items 10.00/10.00% (S\$)					167.69	167.69
Total Parts (S\$)					1,509.21	1,509.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE SIDE MIRROR -RH }	New	200.00	120.00
2	TO RESET & RECALIBRATE SIDE MIRROR CAMERA -RH }	New	300.00	0.00
3	TO RESPRAY PAINT ON SIDE MIRROR COVER -RH	New	120.00	50.00
Gross Labour Cost (S\$)			620.00	170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >