

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 5821D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	955.80	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	521.40	-
1	FRONT LH SIDE MIRROR ASSEMBLY	TO REPAIR SEE LABOUR	1,104.00	-
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	711.00	-
1	FRONT LH ALLOY SPORTS RIM	SCRATCHED	699.00	629.10
1	FRONT LH WHEEL TRIM MOULDING	SCRATCHED	267.00	200.00
	LESS 20% DISCOUNT		-851.64	-165.82
			3,406.56	663.28
	<u>LABOUR</u>			
	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT PORTIONS; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT LH FENDER, FRONT LH SIDE MIRROR ASSEMBLY AND FRONT LH DOOR.		600.00	600.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS.		120.00	30.00
	TO CHECK WIRING.		180.00	40.00
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT. (NPA)	NOT NECESSARY	-	-
	SPRAY PAINTING FOR FRONT PORTIONS AFFECTED PARTS.		750.00	680.00
	REFOCUSING OF THE FRONT HEADLAMP. (NPA)	NOT NECESSARY	-	-
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE. (NPA)	NOT NECESSARY	-	-
	3D WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO APPLY WATERPROOFING SEALER ON FRONT SUPPORT PANELS. (NPA)	NOT NECESSARY	-	-
			1,770.00	1,350.00
	GRAND TOTAL		5,176.56	2,013.28

Report Ref No. CS/INC23001754/Sny3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC23001754/Sny3m4

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser