

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	NCE LTD	Ref:	CS3/INC23001755/Swy3m4	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557	Date:	09/03/2023	
	ATTN: CHRYLLIS	QUAH	Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SNH 2777X	Veh. Inspected	SME 4403P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1208064-002	Excess (\$)	0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	16/02/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JHMRU1810GX200642	Colour	BLACK	
	Odometer	305723 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	MICHELIN	5 mm	
	L/H Front Tyre	215/55 R17	MICHELIN	5 mm	
	R/H Rear Tyre	215/55 R17	MICHELIN	5 mm	
	L/H Rear Tyre	215/55 R17	MICHELIN	5 mm	
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA			
5.	General Information				
	Accident Date	28/01/2023	Inspect Date / Time	16/02/2023 ( 01:30 PM )	
	Survey held at	RS GARAGE SERVICES PTE L	ΓD		
		BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875			
5a.		Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC23001755/Swy3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser