

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001757/KQP3Q2**Date:** 27/03/2023**REFERENCE**

|                              |   |                             |                        |
|------------------------------|---|-----------------------------|------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNA00006712303     |
| <b>Claimant Vehicle No :</b> | SLD2147J                                      | <b>Insured Vehicle No :</b> | XE4936M                |
| Date of Loss:                | 11/02/2023                                    | Nature of Claim:            | TP                     |
|                              |   | Claim No:                   | SNM23D201155/C02/IRENE |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLD2147J</b>                   | Engine No:  | 27492030584104    |
| Make & Model:               | MERCEDES-BENZ E250, 1.8 (A)       | Chassis No: | WDD2120362B312977 |
| Reg. Date:                  | 08/06/2016 (Man. Year: 2015)      | Odometer:   | 70790 km          |
| Colour:                     | Metallic Black                    |             |                   |
| Engine Capacity:            | 1991 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 245/40 R18   | Rear Tyre Size:  | 245/40 R18   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 10,439.00         | 3,570.30          | 6,868.70          | 65.80         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,980.00          | 1,360.00          | 2,620.00          | 65.83         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>14,419.00</b>  | <b>4,930.30</b>   | <b>9,488.70</b>   | <b>65.81</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>3,950.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>14,419.00</b>  | <b>3,950.00</b>   | <b>10,469.00</b>  | <b>72.61</b>  |

**INSPECTION**

|                             |            |               |   |
|-----------------------------|------------|---------------|---|
| Date of Assignment:         | 16/02/2023 |               |   |
| Date Inspected:             | 16/02/2023 | Inspected At: | Kent Seng Car Service<br>Blk 1017 Yishun Industrial Park A, #01-240<br>Singapore 768759 |
| Estimated Period of Repair: | 5.0 days   |               |   |

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

|   |  |
|---|--|
| <b>Reference</b>  |  |
| <b>Part Source:</b> MRM-SG  | Version: 1.0 (Last Synchronised: 27 Mar 2023)                |
| <b>Parts:</b> 143   | MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b> Repairer's   | (Price-denominated Standard List)                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SLD2147J)  |  |
| <b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

## Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition            | Repairer's | Amount       |
|-----|-----|----------|---------------------------------------|----------------------|------------|--------------|
| 1   | 1   |          | *REAR BUMPER                          | Buckled              | 1,641.00 F | *1,558.00 FL |
| 2   | 10  |          | *REAR BUMPER CLIPS                    | Necessary            | 60.00 F    | *60.00 FL    |
| 3   | 2   |          | *REAR BUMPER SIDE RETAINER            | Serviceable          | 82.00 F    | *- FL        |
| 4   | 2   |          | *REAR BUMPER SIDE BRACKET             | Serviceable          | 154.00 F   | *- FL        |
| 5   | 1   |          | *REAR BUMPER LOWER LIP PROTECTOR      | Dented               | 546.00 F   | *546.00 FL   |
| 6   | 1   |          | *REAR BUMPER LOWER CHROME MOULDING    | Serviceable          | 359.00 F   | *- FL        |
| 7   | 4   |          | *REAR BUMPER LEFT SIDE REVERSE SENSOR | Shorted (2 PCS ONLY) | 1,056.00 F | *468.00 FL   |
| 8   | 1   |          | *REAR BUMPER REINFORCEMENT            | Buckled              | 814.00 F   | *670.00 FL   |
| 9   | 1   |          | *REAR BUMPER TOW COVER                | Serviceable          | 68.00 F    | *- FL        |
| 10  | 2   |          | *REAR EXHAUST CHROME COVER (LH & RH)  | Serviceable          | 704.00 F   | *- FL        |
| 11  | 1   |          | *REAR BOOT LID NUMBER PLATE GARNISH   | Serviceable          | 279.00 F   | *- FL        |
| 12  | 2   |          | *REAR BOOT LID REFLECTOR (LH & RH )   | Serviceable          | 880.00 F   | *- FL        |
| 13  | 1   |          | *REAR BOOTL LID E250 EMBLEM           | Necessary            | 79.00 F    | *79.00 FL    |
| 14  | 1   |          | *REAR BOOTL LID TG-TRONIC EMBLEM      | Necessary            | 85.00 F    | *85.00 FL    |
| 15  | 1   |          | *REAR BOOT LID MERCEDES LOGO          | Necessary            | 125.00 F   | *125.00 FL   |
| 16  | 1   |          | *REAR BOOT LID TOP LOCK               | Dented               | 376.00 F   | *376.00 FL   |
| 17  | 1   |          | *REAR END PANEL                       | Repair               | 1,539.00 F | *- FL        |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH           | Serviceable          | 136.00 F   | *- FL        |
| 19  | 8   |          | *REAR END PANEL TOP GARNISH CLIPS     | Not Necessary        | 48.00 F    | *- FL        |
| 20  | 2   |          | *TAIL LAMP (LH & RH )                 | Serviceable          | 1,408.00 F | *- FL        |

F=Franchise part. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (S\$)</b>                                   | <b>10,439.00</b> | <b>3,967.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (S\$)</b> | 0.00             | 396.70          |
| <b>Total Parts (S\$)</b>                                 | <b>10,439.00</b> | <b>3,570.30</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>            |   |          |                 |                 |
| 1                              | APPLY ANTI RUST AND SEALANT FOR ACCIDENT REPAIRED AREA  | New      | 150.00          | 0.00            |
| 2                              | STRAIGHTENING ,REPAIRING AND REALIGNING ONTO THE REAR AFFECTED AREA ,CUTTING REAR END PANEL ,KNOCKING REAR SPARE TYRE TANK PANEL,DISMANTLE AND REPLACE THE ABOVE AFFECTED PARTS | New      | 2,000.00        | 550.00          |
| 3                              | SPRAY PAINTING FOR ALL ACCIDENT AFFECTED PARTS ,REAR BUMPER ,REAR REINFORCEMENT BAR ,REAR END PANEL,REAR BOOT LID & REAR SPARE TYRE TANK PANEL                                  | New      | 1,500.00        | 750.00          |
| 4                              | REPROGRAMMED THE ERROR CODES AFTER THE ACCIDENT REPAIR WORKS  | New      | 250.00          | 0.00            |
| 5                              | TO TESTING ,CHECKING ,DISMANTLE & REPLACE REAR BUMPER REVERSE SENSOR  | New      | 80.00           | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>3,980.00</b> | <b>1,360.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >