

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23001758/KPA3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000519997-01
Claimant Vehicle No :	GBK5943P	Insured Vehicle No :	SJJ8705B
Date of Loss:	07/02/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK5943P	Engine No:	K9KF647D096752
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)	Chassis No:	VF1FWT8H363804733
Reg. Date:	23/09/2020 (Man. Year: 2019)	Odometer:	36579 km
Colour:	Red/White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 9 mm	Rear Left Side:	Nexen 9 mm
Front Right Side:	Nexen 9 mm	Rear Right Side:	Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,440.00	4,331.00	5,109.00	54.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	670.00	410.00	37.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,520.00	5,001.00	5,519.00	52.46
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	10,520.00	4,000.00	6,520.00	61.98
+ GST 8.00/8.00% (S\$)	841.60	320.00	521.60	61.98
Nett Amount (S\$)	11,361.60	4,320.00	7,041.60	61.98
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,722.00		

INSPECTION

Date of Assignment:	16/02/2023	
Date Inspected:	20/02/2023	Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts: 143	mitsubishi LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK5943P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHR DOOR	Bent	2,800.00 FL	*1,900.00 FL
2	1		*RHR DOOR	Bent	2,800.00 FL	*1,790.00 FL
3	1		*REAR BUMPER	Buckled	1,200.00 FL	*750.00 FL
4	1		*REAR BUMPER BRACKET	Repair	600.00 FL	*- FL
5	1		*RERVERSE SENSORS	Serviceable	750.00 FL	*- FL
6	1		*EMBLEM KANGOO	Necessary	220.00 FL	*130.00 FL
7	1		*EMBLEM MAXI	Necessary	220.00 FL	*60.00 FL
8	1		*REAR TRUNK LOCK	Repair	560.00 FL	*- FL
9	2		*REAR TRUNK HINGE UPPER	Repair	350.00 FL	*- FL
10	2		*REAR TRUNK HINGE LOWER	Repair	350.00 FL	*- FL
11	2		*REAR DOOR WINDOW MOULDING	Serviceable	250.00 FL	*- FL
12	1		*ARTWORK	Necessary	180.00 FS	*100.00 FS
13	1		*STICKER 70KM/H	Necessary	30.00 FS	*12.00 FS
14	1		*STICKER 5 PAX	Necessary	30.00 FS	*12.00 FS
15	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*NO PLATE EMBROSS WHITE WORDING	Serviceable	35.00 FS	*- FS
17	1		*NO PLATE CASING	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,450.00	4,794.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,010.00	463.00
Total Parts (\$)	9,440.00	4,331.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY LHR DOOR ,RHR DOOR ,REAR BUMPER	New	750.00	500.00
2	TO REMOVE AND REFIT REAR DOOR GLASS LH & RH	New	250.00	120.00
3	TO CHECK WIRING ,REVERSE SENSOR	New	80.00	50.00
			Gross Labour Cost (S\$)	1,080.00
				670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >