

ASS. REC. BY:

REF:

AG2/23001760/kv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

STN 379R Yr Regn: 01, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda 1-17 c.c. 1339

Colour:

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading:

221566 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GEG 1149092

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

13/2/2

Rear

R/Bal.

7 mm

L/Bal.

7 mm

D.O.I.

16/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

ASS. REC. BY:

REF:

AG2/23001760/kv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

STN 379R Yr Regn: 01, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda 1-17 c.c. 1339

Colour:

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading:

221566 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GEG 1149092

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

13/2/2

Rear

R/Bal.

7 mm

L/Bal.

7 mm

D.O.I.

16/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

ASS. REC. BY:

REF:

AG2/23001760/kv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

STN 379R Yr Regn: 01, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda 1-17 c.c. 1339

Colour:

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading:

221566 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GEG 1149092

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

13/2/2

Rear

R/Bal.

7 mm

L/Bal.

7 mm

D.O.I.

16/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA & EH not ready, P.A. for jammed
C/A wheel @ 2275.00

9/13 11:30 @ 4400 C.A. (red 10,131.20, 69%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2) 13/3/23-typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation

S - RS. \$

F. 1/15

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / L.B. (\$ 4400

TOTAL

Not Authorized
11/20/98 @ 4400h
Penny After Pain
6 days


Mobile: 82636295 Email: thiamhenghuat@gmail.com

Date: 24/02/2023

Claim Type: TP

VRN: SJN379R

Damaged area: Rear



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper <i>485.40</i>	<i>R</i> 1	\$ 726.00	\$ 726.00
2	Rear bumper bracket	<i>N/P</i> 2	\$ 29.35	\$ 58.70
3	Rear bumper side retainer	<i>R</i> 2	\$ 33.00	\$ 66.00
4	Rear bumper tow hook cover	<i>R</i> 1	\$ 24.50	\$ 24.50
5	Rear fender	<i>R</i> 2	\$ 559.00	\$ 1,118.00
6	Rear fender glass moulding	<i>R</i> 2	\$ 68.90	\$ 137.80
7	Rear fender inner garnish	<i>old Di's</i> 2	\$ 396.00	\$ 792.00
8	Rear fender inner trimboard	<i>Replaced</i> 2	\$ 496.30	\$ 992.60
9	Rear fender cowl	<i>R</i> 2	\$ 87.90	\$ 175.80
10	Spare wheel panel	<i>R</i> 1	\$ 737.00	\$ 737.00
11	Rear air vent	<i>R</i> 1	\$ 52.00	\$ 52.00
12	Rear dust cover	<i>R</i> 1	\$ 47.70	\$ 47.70
13	End panel	<i>R</i> 1	\$ 465.10	\$ 465.10
14	End panel top garnish	<i>new Di's</i> 1	\$ 189.00	\$ 189.00
15	Tailgate <i>845.30</i>	<i>R</i> 1	\$ 1,168.00	\$ 1,168.00
16	Tailgate "FIT" emblem	<i>New</i> 1	\$ 38.50	\$ 38.50
17	Tailgate "HONDA" Logo	<i>New</i> 1	\$ 26.00	\$ 26.00
18	Tailgate inner trimboard	<i>R</i> 1	\$ 296.30	\$ 296.30
19	Tailgate outer garnish	<i>R</i> 1	\$ 238.00	\$ 238.00
20	Tailgate outer handle	<i>R</i> 1	\$ 98.00	\$ 98.00
21	Tailgate top lock	<i>Rd</i> 1	\$ 186.20	\$ 186.20
22	Tailgate lock striker	<i>R</i> 1	\$ 89.40	\$ 89.40
23	Tailgate weatherstrip	<i>Rd Di's</i> 1	\$ 165.00	\$ 165.00
24	Tailgate wiper arm cover	<i>Di's</i> 1	\$ 15.00	\$ 15.00
25	Tailgate wiper motor	<i>R</i> 1	\$ 386.00	\$ 386.00
26	Tailgate wiper blade	<i>R</i> 1	\$ 38.00	\$ 38.00
27	Tailgate wiper blade arm	<i>R</i> 1	\$ 48.00	\$ 48.00
28	Windscreen moulding	<i>New</i> 1	\$ 182.00	\$ 182.00
29	Taillamp <i>288.50 old BRN</i> <i>N/S m/bm</i>	2	\$ 376.20	\$ 752.40
30	Taillamp lower bracket	<i>R</i> 2	\$ 31.20	\$ 62.40
31	Taillamp panel <i>old BRN</i>	2	\$ 185.80	\$ 371.60
32	Rear wheel panel tool box	<i>ENT</i> 1	\$ 238.00	\$ 238.00
33	Rear wheel panel trimboard	<i>R</i> 1	\$ 296.70	\$ 296.70
34	Rear number plate lamp	<i>R</i> 2	\$ 48.00	\$ 96.00
35	Exhaust muffler	<i>R</i> 1	\$ 786.80	\$ 786.80

Repair Estimate

36	Exhaust muffler heatshield	1	\$ 112.00	\$ 112.00	X
37	Exhaust muffler mounting	2	\$ 37.00	\$ 74.00	X
38	Rear bumper reinforcement	1	\$ 442.00	\$ 442.00	X
39	Rear bumper reinforcement bracket	2	\$ 159.00	\$ 318.00	X
Subtotal				\$ 12,106.50	
List discount				20.00%	
Total				\$ 9,685.20	

Special nett items

No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper clips	12	\$ 5.50	\$ 66.00	11
2	End panel inner garnish clip	8	\$ 5.50	\$ 44.00	11
3	Rear fender inner garnish clips	16	\$ 5.50	\$ 88.00	4
4	Rear fender inner trimboard clips	16	\$ 5.50	\$ 88.00	11
5	Rear fender cowling clips	12	\$ 5.50	\$ 66.00	X
6	Spare wheel panel sealant	1	\$ 120.00	\$ 120.00	X
7	End panel sealant	1	\$ 120.00	\$ 120.00	30cm
8	End panel top garnish clips	8	\$ 5.50	\$ 44.00	X
9	Tailgate inner trimboard clips	10	\$ 5.50	\$ 55.00	X
10	Rear windscreen sealant	1	\$ 120.00	\$ 120.00	40cm
11	Reverse sensors	1	\$ 280.00	\$ 280.00	20cm
12	Rear number plate & frame	1	\$ 55.00	\$ 55.00	X
13	Sundries	1	\$ 50.00	\$ 50.00	X
Total				\$ 1,196.00	

Labour

No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00	900l
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	20l
3	To remove, refit tailgate components, check and re-adjust close gap, alignment and water seepage.	0.75	\$ 150.00	60l
4	To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test distance and functions.	0.75	\$ 150.00	30l
5	To remove and refit, straighten and re-adjust exhaust pipe and replace exhaust silencer.	0.75	\$ 150.00	X
6	To remove and refit both rear fender glass to facilitate repair work.	1.5	\$ 300.00	X
7	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00	120l
8	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00	900l
9	To rust proof all affected portions after repair.	0.5	\$ 100.00	60l
Total labour			\$ 3,650.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Grand Total \$ 14,531.20