

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS3/FCI23001765/Wvy3m4	
	16 RAFFLES QUAY #42-01 HONG LEO SINGAPORE 0485	NG BUILDING	Date:	21/02/2023	
			Code:	FCI2	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMM 2784K	Veh. Inspected	SLR 9038X	
	Policy No.	D-23100460MFQC/69	Coverage (\$)	0.00	
	Claim No.	D23000559MFQC	Excess (\$)	0.00	
	Assign From	CAROLINE CABRERA	Assign Date	16/02/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL HYBRID	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	RU31249246	Colour	BLACK	
	Odometer	76192 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/50 R17	HABILEAD	6 mm	
	L/H Front Tyre	225/50 R17	HABILEAD	6 mm	
	R/H Rear Tyre	225/50 R17	HABILEAD	6 mm	
	L/H Rear Tyre	225/50 R17	HABILEAD	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S			
5.	General Information				
	Accident Date	13/02/2023	Inspect Date / Time	16/02/2023 (04:00 PM)	
	Survey held at	BLK 7 SIN MING IND EST SECT	OR C #01-82/ #01-80		
	Repairer	GUAN AUTO SERVICE			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/FCI23001765/Wvy3m4

Inspected By

Asst. Automotive Assessor

MUHAMMAD AKID BIN MOHAMED KAMAL

D)MARKET VALUE:\$64,000.00

K.K.LAU CPT(RET) $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser