



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 7936J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	CRACKED	792.40	690.00
20	FRONT BUMPER CLIPS @\$5.50 (CONSISTENT)	NECESSARY	110.00	20.00
1	FRONT BUMPER BRACKET (CONSISTENT)	CRACKED	79.70	79.70
1	FRONT GRILLE (CONSISTENT)	CRACKED	477.40	280.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	CRACKED	154.90	130.00
1	HEAD LAMP (CONSISTENT)	CRACKED	784.70	300.00
1	FRONT FOG LAMP COVER (CONSISTENT)	CRACKED	88.60	60.00
1	FRONT FOG LAMP (CONSISTENT)	CRACKED	466.00	260.00
1	FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	937.30	-
1	FRONT FENDER INNER LINER (CONSISTENT)	CUT	235.60	90.00
1	FRONT BUMPER REINFORCEMENT (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	FRONT BUMPER REINFORCEMENT FOAM (NPA) (CONSISTENT)	NOT FITTED	-	-
1	WINDSCREEN WATER TANK (CONSISTENT)	DENTED	192.50	85.00
1	WINDSCREEN WATER PUMP (CONSISTENT)	NOT NECESSARY	220.40	-
1	ABS PUMP (CONSISTENT)	NOT NECESSARY	2,180.30	-
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,082.40	-
1	AIRCON PIPE (CONSISTENT)	DENTED	480.00	160.00
	LESS 25% DISCOUNT		-	-538.68
			8,282.20	1,616.02
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER, FRONT BUMPER REINFORCEMENT AND FRONT SUPPORT PANEL.		700.00	600.00
	SPRAY PAINT.		700.00	600.00
	AIRCON PIPE LABOUR.		40.00	40.00
	RESET ABS CODE.		40.00	40.00

Report Ref No. CS/HSB23001766/Sqp3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	ABS PUMP LABOUR (NPA).	NOT NECESSARY	-	-
			1,480.00	1,280.00
GRAND TOTAL			9,762.20	2,896.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CS/HSB23001766/Sqp3m4

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.