No.

23799

Insurance Loss Adjusters and Licensed Appraisers Regn.52868584L Blk 131 Rivervale Street #05-872 S'pore 540131Tel:96824663 E-mail: prestigeappraiserservices@yahoo.com.sg

INVOICE =

Customer

To

Mr Muhammad Heikel Bin Azmi c/o 61 Woodlands Industrial Park E9

#01-19

Singapore 757047

Date Our ref Your Ref

30-Dec-22 PS/013/12/22

VEHICLE REGISTRATION NO: FBS 6020 D

VEHICLE MAKE/MODEL : Yamhaha T155

INSPECTION REPORT FEES

(inclusive of photographs & transport charges)

\$440.00

DOLLARS: Four Hundred And Forty Only

E. &. O. E.

for PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:96824663 E-mail: prestigeappraiserservices@yahoo.com.sg

Our ref: PS/013/12/22

Date: 30th December 2022

Mr Muhammad Heikel Bin Azmi c/o 61 Woodlands Industrial Park E9 #01-19 Singapore 757047

Dear Sir.

Re: THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle FBS 6020 D on 21st December 2022.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by Messrs. THCycle Pte Ltd for \$8,127.00 as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of \$5,400.00 lump sum corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be FOUR (4) days. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI

Dip. MTM. Automotive Engineer

Licensed Appraiser

Encl.

#### VEHICLE INSPECTION REPORT

To: Mr Muhammad Heikel Bin Azmi

Singapore 757047

c/o 61 Woodlands Industrial Park E9

Date Our Ref : 30th December 2022

#01-19

Policy No

Sum Insured Excess

: T/P Claim

: PS/013/12/22

Assigned By

: Mr Muhammad Heikel Bin Azmi

Assignment Date : 21st December 2022
Accident Date : 30th August 2022
Inspection Date : 21st December 2022
Workshop Name : THCycle Pte Ltd

Survey Conducted At : 61 Woodlands Industrial Park E9

#01-19

Singapore 757047

#### PARTICULARS OF VEHICLE

Registration No : FBS 6020 D

Mileage

Make/Model

: Yamhaha T155

Engine No : HIDDEN
Chassis No : RLCUG1610MY001064

Make/Model : Yamhaha Ta Type Of Body : Motorcycle

Year Of Manu./Regn. : 2021

Passenger Cap. : 1 Passenger

Colour

: Met. Grey

Others : -

#### **CONDITION OF TYRES**

Front Tyre Rear Tyre

: 4mm 90/80-17 Bridgestone : 4mm 90/80-17 Bridgestone

The above represent the estimated remaining life of the tyre treads.

#### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake

: Serviceable

Body Work

: Good

Footbrake

: Serviceable

Paint Work

: Good

Steering

: Serviceable

Others

. -

#### **POINT OF IMPACT**

The vehicle sustained impacts on the front, L/H & R/H portion.

#### GENERAL DESCRIPTION OF DAMAGES

The front fork, handle bar, main body frame were dented.

For details of damages please refer to schedule attached.

#### **REMARKS:**

At time of inspection, the parts had already dismantled.

This survey was conducted strictly without prejudice.

Vehic	Our Ref:		PS/013/12/22			
Qty	Descriptions LIST ITEMS	Conditions		Repairer's Est.		Our Revised.
1	cover - side 1	sliced	\$	105.00	\$	105.00
1	cover - side 2	sliced		105.00	+	105.00
1	cover - side 3	cracked		168.00		168.00
1	cover - side 4	sliced		168.00		168.00
1	graphic 1 sticker emblem	necessary		38.00		38.00
1	graphic 2 sticker emblem	necessary		38.00		38.00
1	graphic 3 sticker emblem	necessary		35.00		35.00
1	steering cone	necessary		180.00		180.00
1	under bracket	dented		350.00		350.00
2	front fork	dented/warped		600.00		
1	handle bar	bent		160.00		600.00
1	front footrest bar	bent		200.00		160.00
1	shift pedal	sliced		80.00		200.00
1	panel - inner 1	sliced		260.00		80.00
1	panel - front cover	cracked		185.00		260.00 185.00
1	panel - inner 2	cracked		220.00		220.00
1	cover 3 - rear panel	scratched		95.00		
1	cover - centre console	cracked		90.00		95.00 90.00
1	panel 1 - L/H fairing	sliced		125.00		
1	cover - L/H under fairing	sliced				125.00
1	panel 2 - R/H fairing	sliced		80.00 125.00		80.00
1	R/H air guide - under inner fairing	serviceable				125.00
1	L/H air guide - under inner fairing	dented		68.00		-
1	cover - R/H under fairing	serviceable		68.00		68.00
1	cover - under fairing bottom	dented		80.00		-
1	fender	sliced		85.00		85.00
1	cover 1 - L/H centre fairing	sliced		98.00 145.00		98.00
1	cover 2 - R/H centre fairing	serviceable		145.00		145.00
1	panel 3 - L/H centre fairing	sliced				05.00
1	panel 4 - R/H centre fairing	serviceable		85.00		85.00
1	L/H fairing emblem			85.00		-
1	R/H fairing emblem	necessary		25.00		25.00
1	front cover -graphic 5 panel	necessary		25.00		25.00
1	front cover -graphic 6 panel	necessary		25.00		25.00
1	L/H fairing - graphic 7	necessary		25.00		25.00
1	R/H fairing - graphic 8	necessary		35.00		35.00
1	L/H centre fairing - graphic 11	necessary		35.00		35.00
1		necessary		20.00		20.00
2	L/H centre fairing - graphic 12 centre fairing emblem	necessary		20.00		20.00
1	headlamp stay	necessary		86.00		86.00
1	headlamp	dented		185.00		185.00
1	neadiamp	broken		1,650.00		1,650.00
		1 400/		6,397.00		6,019.00
		Less 10%	_			601.90
		Balance c/f	\$	6,397.00	\$	5,417.10

Vehicle No: FBS 6020 D				Our Ref:	PS/013/12/22
Qty	Descriptions	Conditions		Repairer's Est.	Our Revised.
	<u>Labour Charges &amp; Misc</u> To dismantle & replace damage	Balance b/d	\$	6,397.00	\$ 5,417.10
necessary.		u parts, parier beat where		850.00	680.00
	To putty, apply primer & spray-paint on the affected portion.			600.00	400.00
	To align main body frame.		\$	280.00 8,127.00	\$ 250.00 6,747.10

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of \$5,400.00 lump sum corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FOUR ( 4 )** days.
Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer













































































