

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI23001768/AQY3Q2**Date:** 18/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SMA4987S **Insured Vehicle No :** XD5155Z  
 Date of Loss: 15/02/2023 Nature of Claim: TP Claim No: CDMCG23000376

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA4987S**  
 Make & Model: HONDA JAZZ, 1.3 (A) Engine No: L13B11030779  
 Reg. Date: 11/06/2018 (Man. Year: 2018) Chassis No: JHMGK3850JX222806  
 Colour: White Odometer: 66975 km  
 Engine Capacity: 1318 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,861.04	3,342.72	4,518.32	57.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	2,350.00	1,200.00	33.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,411.04</b>	<b>5,692.72</b>	<b>5,718.32</b>	<b>50.11</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>(S\$)</b>	11,411.04	4,500.00	6,911.04	60.56
<b>+ GST 8.00/8.00% (S\$)</b>	912.88	360.00	552.88	60.56
<b>Nett Amount (S\$)</b>	<b>12,323.92</b>	<b>4,860.00</b>	<b>7,463.92</b>	<b>60.56</b>

INSPECTION

Date of Assignment: 16/02/2023  
 Date Inspected: 16/02/2023 Inspected At: N-51 Automotive Pte Ltd (HQ)  
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT  
 AUTOHUB  
 Singapore 417921  
 Estimated Period of Repair: 9.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS**

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
<b>Parts:</b> 144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMA4987S)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	551.50 FL	*551.50 FL
2	1		*REAR BUMPER GUIDE COVER L/R	O/S Deformed	96.20 FL	*48.10 FL
3	1		*REAR BUMPER SIDE RETAINER L/R	O/S Damaged	23.00 FL	*11.50 FL
4	1		*REAR END PANEL	Dented	505.40 FL	*399.00 FL
5	1		*REAR END PANEL INNER TOP GARNISH	Deformed	60.80 FL	*60.80 FL
6	1		*REAR RH FENDER INNER TRIM GARNISH	Not Necessary	199.70 FL	*- FL
7	1		*REAR FLOOR PANEL SPONGE TRAY	Not Necessary	127.30 FL	*- FL
8	1		*REAR FLOOR PANEL TOP BOARD COVER	Not Necessary	189.90 FL	*- FL
9	1		*REAR RH FENDER	Distorted	588.30 FL	*588.30 FL
10	1		*REAR RH FENDER GLASS MOULDING	Necessary	56.90 FL	*56.90 FL
11	1		*REAR RH FENDER INNER AIR VENT	Cracked	38.50 FL	*38.50 FL
12	1		*REAR RH FENDER INNER LOWER SHIELD	Deformed	35.70 FL	*35.70 FL
13	1		*REAR RH FENDER INNER SHIELD	Deformed	149.80 FL	*149.80 FL
14	1		*REAR RH TAILLAMP PANEL	Repair	108.90 FL	*- FL
15	1		*REAR BUMPER CENTER MOULDING	Deformed	91.00 FL	*91.00 FL
16	1		*REAR TAILGATE	Dented	1,071.10 FL	*885.00 FL
17	1		*REAR TAILGATE JAZZ EMBLEM	Necessary	89.40 FL	*89.40 FL
18	2		*REAR TAILGATE DAMPER L/R	Not Necessary	213.60 FL	*- FL
19	2		*REAR TAILGATE HINGES L/R	Not Necessary	66.40 FL	*- FL
20	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	18.50 FL	*- FL
21	2		*REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	Not Necessary	31.00 FL	*- FL
22	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	63.70 FL	*63.70 FL
23	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	78.90 FL	*- FL
24	1		*REAR TAILGATE OUTER BLACK HANDLE	Not Necessary	133.40 FL	*- FL
25	1		*REAR TAILGATE WEATHERSTRIP	Cut	92.30 FL	*92.30 FL
26	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	224.70 FL	*98.00 FL
27	1		*REAR RH TAILLAMP	Cracked	268.90 FL	*268.90 FL
28	1		*REAR AXLE	Not Necessary	911.40 FL	*- FL
29	1		*REAR RH SPORT RIM	Not Necessary	757.90 FL	*- FL
30	1		*REAR RH WHEEL BEARING	Not Necessary	307.20 FL	*- FL
31	1		*REAR RH SHOCK ABSORBER	Not Necessary	245.90 FL	*- FL
32	1		*REAR EXHAUST SILENCER BOX	Not Necessary	552.80 FL	*- FL
33	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	38.80 FL	*- FL
34	1		*REAR RH 185/60R15 TYRE	Not Necessary	480.00 FS	*- FS
35	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
36	1		*SET REAR BUMPER REVERSE SENSOR (4 EYES)	Damaged	450.00 FS	*320.00 FS
37	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
38	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	100.00 FS	*- FS
39	1		*REAR RH FENDER GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
40	1		*SET REAR RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*SET REAR TAILGATE OUTER BLACK HANDLE CLIPS	Not Necessary	40.00 FS	*- FS
43	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
44	1		*SET REAR RH TAILLAMP CLIPS	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 9,458.80 4,048.40**

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL FENDER GLASS	New	100.00	50.00
4	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
5	TO REMOVE,CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE,ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB AND ETC	New	320.00	0.00
6	TO ROAD TEST DRIVING CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
7	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	800.00
8	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	0.00
9	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,300.00	1,100.00
10	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
11	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,550.00</b>	<b>2,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >