

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI23001777/UWY3M4**Date:** 17/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SLA3344R **Insured Vehicle No :** XD5499G

Date of Loss: 16/02/2023 Nature of Claim: TP Claim No: CDMCG23000377

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA3344R**

Make & Model: TOYOTA LEXUS, 2.5 NX300H LUXURY S/R (A) Engine No: 2AR1212853

Reg. Date: 26/12/2014 (Man. Year: 2014) Chassis No: JTJBXRBZX02009781

Colour: Blue Odometer: 113587 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R18 Rear Tyre Size: 235/55R18

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,255.61	15,207.24	9,048.37	37.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	1,760.00	1,760.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,775.61</b>	<b>16,967.24</b>	<b>10,808.37</b>	<b>38.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>27,775.61</b>	<b>13,500.00</b>	<b>14,275.61</b>	<b>51.40</b>

INSPECTION

Date of Assignment: 16/02/2023

Date Inspected: 17/02/2023 Inspected At: JC MOTOR CONSULTANCY  
1 KAKI BUKIT AVE #02-47 AUTOBAY @KAKI  
BUKIT  
SINGAPORE 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	M1-SUV	TOYOTA LEXUS 2.5 NX300H LUXURY S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3344R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,061.38 FN	*1,061.38 FN
2	1		*FRONT BUMPER LED LIGHT - LH	Not Necessary	921.21 FN	*- FN
3	1		*FRONT BUMPER FOG LAMP - LH	Not Necessary	580.65 FN	*- FN
4	1		*FRONT BUMPER SIDE RETAINERS - L/R	N/s Cracked/ O/s Not Necessary	220.50 FN	*110.25 FN
5	1		*FRONT DOOR - LH	Badly Dented	1,678.59 FN	*1,678.59 FN
6	1		*FRONT DOOR OUTER HANDLE	Broken	487.95 FN	*487.95 FN
7	1		*FRONT DOOR OUTER HANDLE COVER	Broken	180.95 FN	*180.95 FN
8	1		*FRONT DOOR SIDE MIRROR ASSY	Damaged/Twisted	2,452.83 FN	*2,452.83 FN
9	1		*FRONT DOOR GLASS OUTER MOULDING	Bent	281.60 FN	*281.60 FN
10	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	311.45 FN	*- FN
11	1		*FRONT DOOR FRAME CHROME MOULDING	Bent/Necessary	261.90 FN	*261.90 FN
12	1		*FRONT DOOR FRAME COVER	Necessary	112.65 FN	*112.65 FN
13	1		*FRONT DOOR INSULATION	Not Necessary	133.20 FN	*- FN
14	1		*FRONT DOOR INNER LOCK	Damaged	978.25 FN	*843.50 FN
15	1		*FRONT DOOR PROTECTOR	Grazed	371.75 FN	*371.75 FN
16	1		*FRONT DOOR W/STRIP	Necessary	282.60 FN	*282.60 FN
17	1		*FRONT FENDER - LH	Repair	981.90 FN	*- FN
18	1		*FRONT FENDER PROTECTOR	Grazed	471.75 FN	*471.75 FN
19	1		*FRONT HEADLAMP ASSY - LH	Scratched/Cracked	4,603.20 FN	*4,603.20 FN
20	1		*FRONT SPORT WHEEL - LH	Repair	2,865.50 FN	*- FN
21	1		*FRONT SHOCK ABSORBER - LH	Not Necessary	691.90 FN	*- FN
22	1		*FRONT KNUCKLE ARM	Not Necessary	981.60 FN	*- FN
23	1		*FRONT WHEEL BEARING	Not Necessary	671.70 FN	*- FN
24	1		*REAR DOOR - LH	Badly Dented	1,487.90 FN	*1,487.90 FN
25	1		*REAR DOOR PROTECTOR	Grazed	381.90 FN	*381.90 FN
26	1		*REAR DOOR GLASS OUTER MOULDING	Bent	281.80 FN	*281.80 FN
27	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	310.65 FN	*- FN
28	1		*REAR DOOR GLASS REGULATOR	Not Necessary	481.95 FN	*- FN
29	1		*REAR DOOR FRAME CHROME MOULDING	Necessary	261.90 FN	*261.90 FN
30	1		*REAR DOOR W/STRIP	Necessary	293.20 FN	*293.20 FN
31	1		*REAR DOOR SEAMING SEAL	Necessary	161.25 FN	*161.25 FN
32	1		*REAR DOOR CHECKER	Not Necessary	110.50 FN	*- FN
33	1		*REAR DOOR INSULATION	Not Necessary	133.20 FN	*- FN
34	1		*REAR DOOR FRAME COVER	Necessary	112.65 FN	*112.65 FN
35	1		*REAR DOOR EMBLEM HYBRID	Necessary	110.35 FN	*110.35 FN
36	1		*REAR FENDER PROTECTOR	Grazed	471.75 FN	*471.75 FN
37	1		*SET REAR BUMPER CLIP	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR DOOR PROTECTOR CLIP	Not Necessary	120.00 FS	*- FS
39	1		*SET REAR DOOR FRAME BLACK TAPE	Necessary	120.00 FS	*60.00 FS
40	1		*SET REAR FENDER PROTECTOR CLIP	Not Necessary	80.00 FS	*- FS
41	1		*SET REAR DOOR PROTECTOR CLIP	Not Necessary	120.00 FS	*- FS
42	1		*SET FRONT DOOR FRAME BLACK TAPE	Necessary	120.00 FS	*60.00 FS
43	1		*SET REAR FENDER PROTECTOR CLIP	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)26,874.0116,883.60

- Nett Item Discount on N Items 10.00/10.00% (S\$)2,618.401,676.36

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						24,255.61 15,207.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX FRONT UNDERCARRIAGE	New	300.00	0.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
4	TO RESPRAY UNDERCOATING	New	150.00	80.00
5	TO RESPRAY PAINTING AND ETC	New	1,400.00	1,000.00
6	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,500.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>3,520.00</b>	<b>1,760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >