



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 2821X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	495.70	-
1	FRONT BUMPER RETAINER LH	CRACKED	64.60	64.60
1	HEADAMP LH	CRACKED	475.00	475.00
1	FRONT FENDER LH	BUCKLED	637.70	637.70
1	FRONT FENDER EMBLEM 'VVT-I'	NECESSARY	48.20	48.20
1	FRONT FENDER INNER SHIELD LH	CRACKED	165.00	165.00
1	FRONT FENDER INNER BRACKET LH	BENT	78.00	78.00
1	FRONT LOWER ARM LH	REFIX	480.00	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	558.90	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	463.80	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	NOT NECESSARY	223.30	-
1	FRONT KNUCKLE ARM BEARING LH	NOT NECESSARY	183.80	-
1	FRONT KNUCKLE HUB LH	NOT NECESSARY	228.90	-
	LESS 25% DISCOUNT		-1,025.73	-367.13
			3,077.17	1,101.37
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE LH - IMPACTED (SN)	REPOLISH	180.00	-
1	FRONT RIM LH (SN)	SCRATCHED	450.00	450.00
1	FRONT BUMPER CLIP (SN)	NECESSARY	50.00	20.00
1	FRONT FENDER INNER SHIELD CLIP LH (SN)	NECESSARY	40.00	20.00
1	FRONT BUMPER LOWER LIP LH (SN)	SCRATCHED	220.00	220.00
			940.00	710.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		630.00	500.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIALS.		500.00	400.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	30.00	-

Report Ref No. CS3/INC22004387/Dny3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIALIST CHARGES - WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	REMOVE AND REPLACE FRONT UNDERCARRIAGE WORK LH.	NOT NECESSARY	225.00	-
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)		36.00	36.00
			1,481.00	936.00
GRAND TOTAL			5,498.17	2,747.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS3/INC22004387/Dny3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.