



AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

T : (65) 6419 3000

www.aig.sg

Claim No: 2979931307SG Date of Survey: 17/03/2023
Repairer: CYCLE & CARRIAGE INDUSTRIES PTE LTD

REFERENCE

Insured: LOONG CHOE YUEN Policy No: 7210032741
Date of Loss: 14/02/2023 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: EH95A
Make & Model: MERCEDES-BENZ E200, 2.0 AVG (A) Reg. Date: 01/04/2021
Engine No: 26492030381400 Chassis No: W1K2130802A940738

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes
		Pre-accident Condition:	

TOTAL OFFER

Offer Authorized By:	LAU, JASON on 26 Apr 2023 11:56
Offer Initiated By:	LAU, JASON on 21 Mar 2023 14:35
Subrogation:	Yes
Rep. Gross Total:	S\$7,762.86 [Diff: S\$2,893.49, 37.27%]
Approved Gross Total:	S\$4,869.36 [Calc.: S\$4,869.37 (Diff: S\$0.01, 0.00%)]
- Excess:	S\$200.00 [Waived: S\$1,000.00] [Remarks: Not Applicable]
	S\$4,669.36
+ GST (8.00%):	S\$373.55
Approved Nett Amount:	S\$5,042.91 (No Betterment/Depreciation)

COST OF CLAIMS

	Repairer's	Our Offer	Difference	Diff %
Parts	4,718.86	2,897.37	1,821.49	38.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,044.00	1,972.00	1,072.00	35.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,762.86	4,869.37	2,893.49	37.27
Approved Total (Overridden) (\$\$)		4,869.36		

- Excess (S\$)	200.00	200.00	0.00	0.00
(S\$)	7,562.86	4,669.36	2,893.50	38.26
+ GST 8.00/8.00% (S\$)	605.03	373.55	231.48	38.26
Nett Amount (S\$)	8,167.89	5,042.91	3,124.98	38.26

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 3.0 days

Authorised Repair : Yes

Inspection conducted by : Lau, Jason (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	2,171.46 FL	*2,171.46 FL	✓
2	1		*REAR BUMPER LOWER TRIM	Cut	389.53 FL	*389.53 FL	✓
3	1		*REAR BUMPER LOWER CHROME MOULDING	Cut	402.10 FL	*402.10 FL	✓
4	2		*REAR DISTANCE SENSOR		613.90 FL	Reuse	
5	2		*DECOUPLING RING		13.44 FL	Reuse	
6	1		*RH/ EXHUAUST PIPE CHROME	Cut	199.16 FL	*199.16 FL	✓
7	1		*RH/ EXHUAUST PIPE CHROME BRACKET		64.34 FL	Reuse	
8	1		*LH/ REAR BUMPER LATERAL SUPPORT		89.31 FL	Reuse	
9	1		*RH/ REAR BUMPER LATERAL SUPPORT		89.31 FL	Reuse	
10	1		*CTR/ BASIC CARRIER FOR BUMPER		113.78 FL	Reuse	
11	1		*REAR CROSS MEMBER		1,039.80 FL	Reuse	
12	1		*REAR BUMPER BRACKET RH	Bent	57.05 FL	*57.05 FL	✓

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,243.18	3,219.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	524.32	321.93
Total Parts (\$\$)	4,718.86	2,897.37

AIG Asia Pacific Insurance Pte. Ltd./EH95A/26/04/2023 11:56

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISASSEMBLE & REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,344.00	672.00 ✓
2	RESPRAY REAR BUMPER	New	1,200.00	800.00 ✓
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT, RESET MEMORY TO IDEN. STD. NETT	New	380.00	380.00 ✓
4	CHECK REAR LIGHTING SYSTEM & WATER TEST FOR ANY LEAKAGE. NETT	New	120.00	120.00 ✓
Gross Labour Cost (\$\$)			3,044.00	1,972.00

AIG Asia Pacific Insurance Pte. Ltd./EH95A/26/04/2023 11:56

< END OF REPORT >

3 days

Fair and resonable