



Your Ref: 2023 - 18

Date: 7th June 2023

Our Ref: CS1/SCD23001779/Dqy3m4

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: EH 95A

INSURED VEHICLE: GBF 6584L

ACCIDENT DATE: 14/02/2023

We thank you for your instruction on 16/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of EH 95A from M/s AIG Asia Pacific Insurance Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicle EH 95A.
- c) Colour damaged vehicle photographs of EH 95A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: EH 95A
Make & Model	: Mercedes Benz E200 Sedan Avg
Chassis Number	: W1K2130802A940738
Year of Registration	: 2021
Engine Capacity	: 1991 cc

2. Our finding is that the repair cost of \$4,869.36 (before GST) quoted by M/s AIG Asia Pacific Insurance Pte Ltd is fair & reasonable.
3. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.

Vehicle Inspected By:



ANG BRYAN TANI

Automotive Assessor / Investigator



K.K.LAU

*MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. EH 95A

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	REAR BUMPER	DEFORMED	2,171.46
1	REAR BUMPER LOWER TRIM	CUT	389.53
1	REAR BUMPER LOWER CHROME MOULDING	CUT	402.10
2	REAR DISTANCE SENSOR (NPA)	REUSE	-
2	DECOUPLING RING (NPA)	REUSE	-
1	RH/ EXHUAUST PIPE CHROME	CUT	199.16
1	RH/ EXHUAUST PIPE CHROME BRACKET (NPA)	REUSE	-
1	LH/ REAR BUMPER LATERAL SUPPORT (NPA)	REUSE	-
1	RH/ REAR BUMPER LATERAL SUPPORT (NPA)	REUSE	-
1	CTR/ BASIC CARRIER FOR BUMPER (NPA)	REUSE	-
1	REAR CROSS MEMBER (NPA)	REUSE	-
1	REAR BUMPER BRACKET RH	BENT	57.05
	LESS 10% DISCOUNT		-321.93
			2,897.37
	<u>LABOUR</u>		
	DISASSEMBLE & REPLACE ATTACHED DAMAGED PARTS & REFINISH.		672.00
	RESPRAY REAR BUMPER.		800.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT, RESET MEMORY TO IDEN. STD. NETT.		380.00
	CHECK REAR LIGHTING SYSTEM & WATER TEST FOR ANY LEAKAGE. NETT.		120.00
			1,972.00
GRAND TOTAL			4,869.37
RECOMMENDED COST OF REPAIRS			4,869.36

Report Ref No. CS1/SCD23001779/Dqy3m4

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.