

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23001787/AWY3Q2**Date:** 24/05/2023**REFERENCE**

Insured/Claimant:	WEE TENG YAU	Policy No:	SP2003942370-01	
Date of Loss:	14/02/2023	Nature of Claim:	OD	Claim No: 202332005452

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG2703B	Engine No:	L15B5671080
Make & Model:	HONDA HR-V, 1.5 DX CVT (A)	Chassis No:	JHMRU1810JX201078
Reg. Date:	14/02/2019 (Man. Year: 2018)	Odometer:	70525 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,620.30	7,285.80	2,334.50	24.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	950.00	330.00	25.78
Paintwork Labour	1,350.00	1,000.00	350.00	25.93
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,250.30	9,235.80	3,014.50	24.61
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	11,750.30	8,735.80	3,014.50	25.65
+ GST 8.00/8.00% (\$\$)	940.03	698.86	241.17	25.66
Nett Amount (\$\$)	12,690.33	9,434.66	3,255.67	25.65

INSPECTION

Date of Assignment:	16/02/2023	Present Location:	Success United Pte Ltd (HQ)
Date Inspected:	17/02/2023	Inspected At:	Success United Pte Ltd (HQ)
			2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
			Singapore 417921
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 May 2023)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG2703B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Dented	420.00 F	*420.00 F
2	2		*Frt bonnet hinges L/R (WCP)	Bent	76.00 F	*76.00 F
3	1		*Frt bonnet Weatherstrip (WCP)	Not Necessary	25.00 F	*- F
4	1		*Frt Bonnet Insulator (WCP)	Not Necessary	90.00 F	*- F
5	1		*Frt Bonnet Lock (WCP)	Damaged	80.00 F	*80.00 F
6	1		*Frt Bonnet Lock bracket (WCP)	Cracked	95.00 F	*95.00 F
7	1		*Frt Fender L/R (WCP)	O/S Buckled	440.00 F	*220.00 F
8	1		*Frt Fender Guard RH (WCP)	Deformed	95.00 F	*95.00 F
9	1		*Frt Bumper (WCP)	Distorted	395.00 F	*395.00 F
10	1		*Frt Bumper Clips	Necessary	30.00 FS	*30.00 FS
11	1		*Frt Bumper Side Holder L/R (WCP)	O/S Damaged	30.00 F	*15.00 F
12	2		*Frt Bumper Bracket L/R (WCP)	Not Necessary	60.00 F	*- F
13	1		*Frt Bumper Tow Hook Cover (WCP)	Deformed	20.00 F	*20.00 F
14	1		*Frt Lower Bumper (WCP)	Deformed	380.00 F	*380.00 F
15	1		*Frt Bumper Lower Air Grille (WCP)	Deformed	78.00 F	*78.00 F
16	1		*Frt Foglamp Garnish L/R (WCP)	O/S Deformed	70.00 F	*35.00 F
17	1		*Frt Grille Base (WCP)	Cracked	220.00 F	*220.00 F
18	1		*Frt Grille Chrome (WCP)	Cracked	190.00 F	*190.00 F
19	1		*Frt Honda logo (WCP)	Necessary	25.00 F	*25.00 F
20	1		*Frt Bumper Reinforcement (WCP)	Bent	250.00 F	*250.00 F
21	1		*Horn (WCP)	Not Necessary	50.00 F	*- F
22	2		*Frt Headlamp L/R (WCP)	Cracked	1,900.00 F	*1,900.00 F
23	1		*Radiator Support Panel Assy (WCP)	Buckled	360.00 F	*360.00 F
24	1		*Radiator (WCP)	Dented	750.00 F	*750.00 F
25	1		*Radiator support top cover garnish (WCP)	Deformed	65.00 F	*65.00 F
26	1		*Radiator support top cover garnish clips	Necessary	30.00 FS	*30.00 FS
27	1		*Radiator Spare Tank (WCP)	Not Necessary	35.00 F	*- F
28	1		*Radiator Lower Hose (WCP)	Not Necessary	25.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*Radiator Auxillary Fan Assy (WCP)	Cracked	350.00 F	*120.00 F
30	1		*Aircon condenser auxillary Fan Assy (WCP)	Cracked	380.00 F	*120.00 F
31	1		*Aircon Liquid pipe (WCP)	Not Necessary	150.00 F	*- F
32	1		*Aircon Discharge Hose (WCP)	Not Necessary	165.00 F	*- F
33	1		*Air Intake duct (WCP)	Not Necessary	55.00 F	*- F
34	1		*Air duct (WCP)	Not Necessary	50.00 F	*- F
35	1		*Air cleaner Housing (WCP)	Cracked	120.00 F	*120.00 F
36	1		*Wiper Garnish assy (WCP)	Not Necessary	190.00 F	*- F
37	1		*Wiper Garnish Clips	Not Necessary	30.00 FS	*- FS
38	1		*Battery terminal cover (WCP)	Cracked	18.00 F	*18.00 F
39	1		*Engine mouting RH (WCP)	Not Necessary	150.00 F	*- F
40	1		*Engine mouting LH (WCP)	Not Necessary	180.00 F	*- F
41	1		*Engine mouting Rear (WCP)	Not Necessary	90.00 F	*- F
42	1		*Radiator top hose (WCP)	Not Necessary	25.00 F	*- F
43	1		*Aircon Condenser (WCP)	Distorted	360.00 F	*360.00 F
44	1		*Frt number plate with frame	Distorted	45.00 FS	*45.00 FS
<u>Supplementary #1</u>						
45	2		*Front headlamp bracket L/R (WCP)	Cracked	76.00 F	*76.00 F
<u>Supplementary #2</u>						
46	1		*Intake manifold pipe (WCP)	Cut	20.00 F	*45.00 F
47	1		*Battery positive terminal cover (WCP)	Repeated	20.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	8,758.00	6,633.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	862.30	652.80
Total Parts (\$\$)	9,620.30	7,285.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	To putty & respray painting on bonnet, bumper, support panel, 2pc fender, fender guard RH, frt door RH.	New	1,200.00	1,000.00
2	To remove, replace engine mounting.	New	150.00	0.00
Labour Items				
3	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	1,000.00	800.00
4	To remove, rearrange electrical wirings, check lighting.	New	100.00	30.00
5	To remove, replace radiator & aircon parts, vacuum & refill gas.	New	180.00	120.00
Gross Labour Cost (\$\$)			2,630.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >