

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU230037
Policy No:	SP2003942370-01	Date of Loss:	14/02/2023
Vehicle Reg. No.:	SMG2703B	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WEE TENG YAU	Contact No:	+6596862197
Driver:	WEE TENG YAU		
Make/Model:	HONDA HR-V, 1.5 DX CVT (A)	Vehicle Reg. Date:	14/02/2019
Vehicle Colour:	Brown		
Engine No:	L15B5671080	Chassis No:	JHMRU1810JX201078
Odometer:	70525 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	9,492.70
Miscellaneous Items	0.00
Labour	1,280.00
Paintwork Labour	1,350.00
Towing	0.00
Calculated Gross Total (S\$)	12,122.70
- Excess (S\$)	500.00
(S\$)	11,622.70
+ GST 8.00% (S\$)	929.82
Nett Amount (S\$)	12,552.52

This claim is handled by: TAN WEI NI

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Feb 2023)
Parts: N/A HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Success United Pte Ltd/SMG2703B/16/02/2023 18:01
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>Deletd</i>	0.00	0.00	*420.00 F ✓
2	2		*Frt bonnet hinges L/R <i>Best.</i>	0.00	0.00	*76.00 F ✓
3	1		*Frt bonnet Weatherstrip <i>new</i>	0.00	0.00	*25.00 F ✓
4	1		*Frt Bonnet Insulator <i>compd</i>	0.00	0.00	*90.00 F ✓
5	1		*Frt Bonnet Lock <i>new</i>	0.00	0.00	*80.00 F ✓
6	1		*Frt Bonnet Lock bracket <i>new</i>	0.00	0.00	*95.00 F ✓
7	2		*Frt Fender L/R <i>RH Buckled</i>	0.00	0.00	*440.00 F <i>240</i>
8	1		*Frt Fender Guard RH <i>new</i>	0.00	0.00	*95.00 F ✓
9	1		*Frt Bumper <i>Distorted.</i>	0.00	0.00	*395.00 F ✓
10	1		*Frt Bumper Clips <i>Na</i>	0	0.00	*30.00 FS ✓
11	2		*Frt Bumper Side Holder L/R <i>new ?</i>	0.00	0.00	*30.00 F ✓
12	2		*Frt Bumper Bracket L/R <i>?</i>	0.00	0.00	*60.00 F ✓
13	1		*Frt Bumper Tow Hook Cover <i>deltd</i>	0.00	0.00	*20.00 F ✓
14	1		*Frt Lower Bumper <i>deltd</i>	0.00	0.00	*380.00 F ✓
15	1		*Frt Bumper Lower Air Grille <i>deltd</i>	0.00	0.00	*78.00 F ✓
16	2		*Frt Foglamp Garnish L/R <i>12H deltd</i>	0.00	0.00	*70.00 F <i>35.</i>
17	1		*Frt Grille Base <i>fauld</i>	0.00	0.00	*220.00 F ✓
18	1		*Frt Grille Chrome <i>new</i>	0.00	0.00	*190.00 F ✓
19	1		*Frt Honda logo <i>new</i>	0.00	0.00	*25.00 F ✓
20	1		*Frt Bumper Reinforcement <i>Best</i>	0.00	0.00	*250.00 F ✓
21	1		*Horn <i>?</i>	0.00	0.00	*50.00 F ✓
22	2		*Frt Headlamp L/R <i>new</i>	0.00	0.00	*1,900.00 F ✓
23	1		*Radiator Support Panel Assy <i>?</i>	0.00	0.00	*360.00 F ✓
24	1		*Radiator <i>?</i>	0.00	0.00	*750.00 F ✓
25	1		*Radiator support top cover garnish <i>deltd</i>	0.00	0.00	*65.00 F ✓
26	1		*Radiator support top cover garnish clips <i>new</i>	0	0.00	*30.00 FS ✓
27	1		*Radiator Spare Tank <i>?</i>	0.00	0.00	*35.00 F ✓
28	1		*Radiator Lower Hose <i>new</i>	0.00	0.00	*25.00 F ✓
29	1		*Radiator Auxillary Fan Assy <i>?</i>	0.00	0.00	*350.00 F ✓
30	1		*Aircon condenser auxillary Fan Assy <i>?</i>	0.00	0.00	*380.00 F ✓
31	1		*Aircon Liquid pipe <i>3m</i>	0.00	0.00	*150.00 F ✓
32	1		*Aircon Discharge Hose <i>3m</i>	0.00	0.00	*165.00 F ✓
33	1		*Air Intake duct <i>?</i>	0.00	0.00	*55.00 F ✓
34	1		*Air duct <i>?</i>	0.00	0.00	*50.00 F ✓
35	1		*Air cleaner Housing <i>new</i>	0.00	0.00	*120.00 F ✓
36	1		*Wiper Garnish assy <i>new</i>	0.00	0.00	*190.00 F ✓
37	1		*Wiper Garnish Clips <i>new</i>	0	0.00	*30.00 FS ✓
38	1		*Battery terminal cover <i>new</i>	0.00	0.00	*18.00 F ✓
39	1		*Engine mouting RH <i>3m</i>	0.00	0.00	*150.00 F ✓
40	1		*Engine mouting LH <i>3m</i>	0.00	0.00	*180.00 F ✓
41	1		*Engine mouting Rear <i>3m</i>	0.00	0.00	*90.00 F ✓
42	1		*Radiator top hose <i>?</i>	0.00	0.00	*25.00 F ✓
43	1		*Aircon Condenser <i>Distorted</i>	0.00	0.00	*360.00 F ✓
44	1		*Frt number plate with frame <i>Distorted</i>	0	0.00	*45.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)

8,642.00

+ Margin on L,N Items 10.00% (\$\$)

850.70

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To putty & respray painting on bonnet, bumper, support panel, 2pc fender, fender guard RH, frt door RH.	New	1,200.00 <i>1000</i>
2	To remove, replace engine mounting.	New	150.00 <i>x</i>
Labour Items			
3	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	1,000.00 <i>800</i>
4	To remove, rearrange electrical wirings, check lighting.	New	100.00 <i>30</i>
5	To remove, replace radiator & aircon parts, vacuum & refill gas.	New	180.00 <i>120</i>
Gross Labour Cost (\$\$)			2,630.00

Success United Pte Ltd/SMG2703B/16/02/2023 18:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Lj

P/P 17/02/23.

Not Authorized

07 Days

Excess : \$500.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: