

Success United Pte Ltd (Co.Reg.No 200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

Xin Yu

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	SU230037
Policy No:	SP2003942370-01	Date of Loss:	14/02/2023
Vehicle Reg. No.:	SMG2703B	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WEE TENG YAU	Contact No:	+6596862197
Driver:	WEE TENG YAU		
Make/Model:	HONDA HR-V, 1.5 DX CVT (A)	Vehicle Reg. Date:	14/02/2019
Vehicle Colour:	Brown		
Engine No:	L15B5671080	Chassis No:	JHMRU1810JX201078
Odometer:	70525 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	9,492.70
Miscellaneous Items	0.00
Labour	1,280.00
Paintwork Labour	1,350.00
Towing	0.00
Calculated Gross Total (S\$)	12,122.70
- Excess (S\$)	500.00
(S\$)	11,622.70
+ GST 8.00% (S\$)	929.82
Nett Amount (S\$)	12,552.52

This claim is handled by: **TAN WEI NI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Feb 2023)
 Parts: N/A HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Success United Pte Ltd/SMG2703B/16/02/2023 18:01
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
50 1	1		*FRONT BONNET <i>Deformed</i>	0.00	0.00	*420.00 F ✓
50 2	2		*Frt bonnet hinges L/R <i>Best</i>	0.00	0.00	*76.00 F ✓
50 3	1		*Frt bonnet Weatherstrip <i>new</i>	0.00	0.00	*25.00 F ✓
50 4	1		*Frt Bonnet Insulator <i>new</i> NN	0.00	0.00	*90.00 F X
50 5	1		*Frt Bonnet Lock <i>new</i>	0.00	0.00	*80.00 F ✓
50 6	1		*Frt Bonnet Lock bracket <i>new</i>	0.00	0.00	*95.00 F ✓
50 7	2		*Frt Fender L/R <i>RH Buckled</i>	0.00	0.00	*440.00 F 220
50 8	1		*Frt Fender Guard RH <i>Deformed</i>	0.00	0.00	*95.00 F ✓
50 9	1		*Frt Bumper <i>Distorted</i>	0.00	0.00	*395.00 F ✓
50 10	1		*Frt Bumper Clips <i>new</i>	0	0.00	*30.00 FS ✓
50 11	2		*Frt Bumper Side Holder L/R <i>new RH and</i>	0.00	0.00	*30.00 F ✓ 15
50 12	2		*Frt Bumper Bracket L/R <i>new</i>	0.00	0.00	*60.00 F ✓
50 13	1		*Frt Bumper Tow Hook Cover <i>new</i>	0.00	0.00	*20.00 F ✓
50 14	1		*Frt Lower Bumper <i>Deformed</i>	0.00	0.00	*380.00 F ✓
50 15	1		*Frt Bumper Lower Air Grille <i>Deformed</i>	0.00	0.00	*78.00 F ✓
50 16	2		*Frt Foglamp Garnish L/R <i>2H Deformed</i>	0.00	0.00	*70.00 F 35
50 17	1		*Frt Grille Base <i>new</i>	0.00	0.00	*220.00 F ✓
50 18	1		*Frt Grille Chrome <i>new</i>	0.00	0.00	*190.00 F ✓
50 19	1		*Frt Honda logo <i>new</i>	0.00	0.00	*25.00 F ✓
50 20	1		*Frt Bumper Reinforcement <i>Best</i>	0.00	0.00	*250.00 F ✓
50 21	1		*Horn <i>new</i>	0.00	0.00	*50.00 F ✓
50 22	2		*Frt Headlamp L/R <i>new</i>	0.00	0.00	*250.00 F ✓
50 23	1		*Radiator Support Panel Assy <i>new</i>	0.00	0.00	*1,900.00 F ✓
50 24	1		*Radiator <i>Deformed</i>	0.00	0.00	*360.00 F ✓
50 25	1		*Radiator support top cover garnish <i>new</i>	0.00	0.00	*750.00 F ✓
50 26	1		*Radiator support top cover garnish clips <i>new</i>	0.00	0.00	*65.00 F ✓
50 27	1		*Radiator Spare Tank <i>new</i>	0	0.00	*30.00 FS ✓
50 28	1		*Radiator Lower Hose <i>new</i>	0.00	0.00	*35.00 F ✓
50 29	1		*Radiator Auxillary Fan Assy <i>new</i>	0.00	0.00	*25.00 F ✓
50 30	1		*Aircon condenser auxillary Fan Assy <i>new</i>	0.00	0.00	*350.00 F 120
50 31	1		*Aircon Liquid pipe <i>new</i>	0.00	0.00	*380.00 F 120
50 32	1		*Aircon Discharge Hose <i>new</i>	0.00	0.00	*150.00 F ✓
50 33	1		*Air Intake duct <i>new</i>	0.00	0.00	*165.00 F ✓
50 34	1		*Air duct <i>new</i>	0.00	0.00	*55.00 F ✓
50 35	1		*Air cleaner Housing <i>new</i>	0.00	0.00	*50.00 F ✓
50 36	1		*Wiper Garnish assy <i>new</i>	0.00	0.00	*120.00 F ✓
50 37	1		*Wiper Garnish Clips <i>new</i>	0	0.00	*190.00 F ✓
50 38	1		*Battery terminal cover <i>new</i>	0.00	0.00	*30.00 FS ✓
50 39	1		*Engine mouting RH <i>new</i>	0.00	0.00	*18.00 F ✓
50 40	1		*Engine mouting LH <i>new</i>	0.00	0.00	*150.00 F ✓
50 41	1		*Engine mouting Rear <i>new</i>	0.00	0.00	*180.00 F ✓
50 42	1		*Radiator top hose <i>new</i>	0.00	0.00	*90.00 F ✓
50 43	1		*Aircon Condenser <i>Deformed</i>	0.00	0.00	*25.00 F ✓
50 44	1		*Frt number plate with frame <i>Distorted</i>	0	0.00	*360.00 F ✓
						*45.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)

+ Margin on L,N Items 10.00% (\$\$)

8,642.00

850.70

6407

+ 10%

7047.70

S.N: 105

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To putty & respray painting on bonnet, bumper, support panel, 2pc fender, fender guard RH, frt door RH.	New	1,200.00 <i>1000</i>
2	To remove, replace engine mounting.	New	150.00 <i>x</i>
Labour Items			
3	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	1,000.00 <i>800</i>
4	To remove, rearrange electrical wirings, check lighting.	New	100.00 <i>30</i>
5	To remove, replace radiator & aircon parts, vacuum & refill gas.	New	180.00 <i>120</i>
Gross Labour Cost (\$\$)			2,630.00

Success United Pte Ltd/SMG2703B/16/02/2023 18:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Lj

P/P 17/02/23.

Not Authorized

07 Days

Excess : \$500.

Supplementary 1: 49.50

Supplementary 2: 83.60

*Total: 923.580 ✓
(P/P)*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(SUPPLEMENTARY)

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU230037
Policy No:	SP2003942370-01	Date of Loss:	14/02/2023
Vehicle Reg. No.:	SMG2703B	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WEE TENG YAU	Contact No:	+6596862197
Driver:	WEE TENG YAU		
Make/Model:	HONDA HR-V, 1.5 DX CVT (A)	Vehicle Reg. Date:	14/02/2019
Vehicle Colour:	Brown		
Engine No:	L15B5671080	Chassis No:	JHMRU1810JX201078
Odometer:	70525 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	44.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	44.00
+ GST 8.00% (S\$)	3.52
Nett Amount (S\$)	47.52
+ Previous Estimates (S\$)	12,642.81
Claim Total (S\$)	12,690.33

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Feb 2023)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Success United Pte Ltd/SMG2703B/24/02/2023 17:19	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Intake manifold pipe ✓ Cut	0.00	0.00	*20.00 F 45
2	1		*Battery positive terminal cover ✓ Deformed	0.00	0.00	*20.00 F X
			<i>Reprinted</i>			
Sub Total (\$\$)						40.00
+ Margin on L,N Items 10.00% (\$\$)						4.00
Total Parts (\$\$)						44.00

F=Franchise part.

Success United Pte Ltd/SMG2703B/24/02/2023 17:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary: 45
+ 10% : 49.50.

(SUPPLEMENTARY)

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU230037
Policy No:	SP2003942370-01	Date of Loss:	14/02/2023
Vehicle Reg. No.:	SMG2703B	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WEE TENG YAU	Contact No:	+6596862197
Driver:	WEE TENG YAU		
Make/Model:	HONDA HR-V, 1.5 DX CVT (A)	Vehicle Reg. Date:	14/02/2019
Vehicle Colour:	Brown	Chassis No:	JHMRU1810JX201078
Engine No:	L15B5671080		
Odometer:	70525 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	83.60
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	83.60
+ GST 8.00% (S\$)	6.69
Nett Amount (S\$)	90.29
+ Previous Estimates (S\$)	12,552.52
Claim Total (S\$)	12,642.81

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Feb 2023)

Parts: N/A HONDA HR-V 1.5 DX CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Success United Pte Ltd/SMG2703B/24/02/2023 11:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
7001	2		*Front headlamp bracket L/R			
			✓ Cracked	0.00	0.00	*76.00 F
			Sub Total (\$\$)			76.00
			+ Margin on L,N Items 10.00% (\$\$)			7.60
			Total Parts (\$\$)			83.60

Success United Pte Ltd/SMG2703B/24/02/2023 11:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary 7: 76
+ 10%: 83.60