

ASS. REC. BY:

REF:

AG21 230017961kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 84885

Yr Regn:

08, 21

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

A7 Nante c.c

15P8

Colour

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading

26336

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KN116N41ETN4 230012

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

205/35R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

15/2/23

D.O.I.

17/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

E4 not ready

15/3 83777.32

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :


Lump Sum / I.B.I. (\$

NOT Withheld
Prescription BY patient

⑧ 3777.32

5 days

Damaged area: Rear



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bootlid	1	\$ 2,032.20	\$ 2,032.20	
2	Bootlid lock	1	\$ 116.20	\$ 116.20	
3	Bootlid hinge	2	\$ 93.00	\$ 186.00	
4	Bootlid weatherstrip	1	\$ 175.00	\$ 175.00	
5	Bootlid inner trim	1	\$ 198.00	\$ 198.00	
6	Bootlid "HYUNDAI" logo	1	\$ 55.00	\$ 55.00	
7	Bootlid lamp assy	1	\$ 1,273.00	\$ 1,273.00	
8	Rear bumper	1	\$ 1,070.80	\$ 1,070.80	
9	Rear bumper side retainer	2	\$ 78.00	\$ 156.00	
10	Rear bumper reinforcement	1	\$ 594.80	\$ 594.80	
11	Rear bumper lower	1	\$ 640.60	\$ 640.60	
12	Rear bumper lower center moulding	1	\$ 97.50	\$ 97.50	
13	Rear bumper lower moulding	1	\$ 198.40	\$ 198.40	
14	Rear bumper reinforcement bracket	5	\$ 44.80	\$ 224.00	
15	Rear bumper reflector	2	\$ 200.40	\$ 400.80	
16	Rear bumper center reflector	1	\$ 301.50	\$ 301.50	
17	Rear bumper licence plate lamp	2	\$ 235.20	\$ 470.40	
18	Bootlid upper cover	1	\$ 298.70	\$ 298.70	
19	Bootlid "AVANTE" emblem	1	\$ 31.20	\$ 31.20	
20	Taillamp	2	\$ 876.80	\$ 1,753.60	
21	Keyless antenna	1	\$ 148.60	\$ 148.60	
22	End panel	1	\$ 454.60	\$ 454.60	
23	End panel top garnish	1	\$ 169.50	\$ 169.50	
24	Spare tyre panel	1	\$ 546.50	\$ 546.50	
25	Spare tyre panel top board	1	\$ 155.30	\$ 155.30	
26	Tools holder	1	\$ 123.90	\$ 123.90	
27	Spare tyre panel insulator	1	\$ 88.60	\$ 88.60	
28	Blind spot sensor	2	\$ 226.90	\$ 453.80	
29	Rear bumper lower side cowl	2	\$ 62.70	\$ 125.40	
Subtotal				\$ 12,539.90	
List discount				20.00%	
Total				\$ 10,031.92	

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper sensor <i>erfo</i>	<i>short 4/1</i>	\$ 280.00	\$ 1,120.00
2	Rear bumper sensor holder	<i>1m</i> 4	\$ 24.00	\$ 96.00
3	Rear bumper sensor wire harness	<i>m</i> 1	\$ 175.00	\$ 175.00
4	Bootlid inner trim board clips	<i>mm</i> 10	\$ 4.50	\$ 45.00
5	Rear bumper clips	<i>mm</i> 10	\$ 4.50	\$ 45.00
6	End panel sealant	<i>mm</i> 1	\$ 100.00	\$ 100.00
7	End panel top garnish clips	<i>mm</i> 10	\$ 4.50	\$ 45.00
8	Spare tyre panel sealant	<i>mm</i> 1	\$ 100.00	\$ 100.00
9	Rear bumper lower side cowling clips	<i>mm</i> 16	\$ 4.50	\$ 72.00
10	Sundries	<i>mm</i> 1	\$ 50.00	\$ 50.00
Total				\$ 1,848.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit bootlid components to replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$ <i>mm</i> 100.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
5	Supply spray paint material and necessary items to respray affected area / panel.	7	\$ 1,400.00
Total labour			\$ 3,350.00

Estimate Grand Total	\$ 15,229.92
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: