

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23001797/SQY3Q2**Date:** 02/05/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS009314	
Claimant Vehicle No :	SH8326R	Insured Vehicle No :	SLQ2356D	
Date of Loss:	14/02/2023	Nature of Claim:	TP	Claim No: M2301036

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8326R	Engine No:	D4FDGU706200
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU098188
Reg. Date:	11/01/2017 (Man. Year: 2016)	Odometer:	1021474 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,336.80	80.00	4,256.80	98.16
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,900.00	1,620.00	280.00	14.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,247.80	1,711.00	4,536.80	72.61
+ GST 8.00/8.00% (S\$)	499.82	136.88	362.94	72.61
Nett Amount (S\$)	6,747.62	1,847.88	4,899.74	72.61

INSPECTION

Date of Assignment:	16/02/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	17/02/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 May 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8326R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Repair	2,416.80 FL	*- FL
2	1		*ROCKER PANEL OUTER GARNISH LH	Repair	732.80 FL	*- FL
3	1		*REAR FENDER LH	Repair	2,171.40 FL	*- FL
4	1		*REAR DOOR COMFORTDELGRO & APPS STICKER LH	Necessary	80.00 F	*80.00 F
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					5,401.00	80.00
- List Item Discount on L Items 20.00/20.00% (S\$)					1,064.20	0.00
Total Parts (S\$)					4,336.80	80.00

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	840.00
2	SPRAY PAINTING CHARGE	New	800.00	750.00
3	TRANSFER OF DOOR	New	120.00	0.00
4	TUFF KOTE	New	80.00	30.00
Gross Labour Cost (\$\$)			1,900.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >