

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	HSBC LIFE (SINGA	APORE) PTE LTD	F	Ref:	CS3/HSB23001803/Wwp3m4	
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	[	Date:	23/02/2023	
	ATTN: LOH CYNTH	HIA	(	Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 4447T	Veh. Inspected		FBK 1004B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S3M04JI8	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		17/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CBR600RR	c.c		599	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JH2PC40C7DK601396	Colour		BLACK	
	Odometer	103504 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/70 ZR17	MICHELIN		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	180/55 ZR17	MICHELIN		5 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	General Information					
	Accident Date	16/11/2022	Inspect Date / T	ime	17/02/2023 ( 12:16 PM )	
	Survey held at	ONG MOTOR TRADING				
		NO. 464 MACPHERSON ROAD SINGAPORE 368182				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/HSB23001803/Wwp3m4

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser