

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23001811/UVY3M4**Date:** 09/03/2023**REFERENCE**

Insured/Claimant:	LIN ZHONGXING	Policy No:	SP2004017370-01	
Date of Loss:	15/02/2023	Nature of Claim:	OD	Claim No: 202332005413

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFD3328T	Engine No:	3ZZ4972248
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106167288
Reg. Date:	10/02/2010 (Man. Year: 2009)	Odometer:	116796 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,021.40	4,811.40	1,210.00	20.09
Miscellaneous Items	65.00	60.00	5.00	7.69
Labour	2,100.00	1,620.00	480.00	22.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,186.40	6,491.40	1,695.00	20.71
Approved Total (Overridden) (S\$)		4,500.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	8,186.40	3,900.00	4,286.40	52.36
+ GST 8.00/8.00% (S\$)	654.91	312.00	342.91	52.36
Nett Amount (S\$)	8,841.31	4,212.00	4,629.31	52.36

INSPECTION

Date of Assignment:	17/02/2023	Present Location:	SME Motor Pte Ltd (Kaki Bukit) SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883
Date Inspected:	20/02/2023	Inspected At:	
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2023)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFD3328T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Buckled	330.00 F	*330.00 F
2	2		*FRT BONNET HINGE (WCP)	Bent	110.00 F	*110.00 F
3	1		*FRT BONNET INSULATOR (WCP)	Warped	145.00 F	*145.00 F
4	10		*FRT BONNET INSULATOR CLIP (WCP)	Necessary	20.00 F	*20.00 F
5	1		*RFT BONNET LOCK CABLE (WCP)	Jammed	65.00 F	*65.00 F
6	1		*FRT BONNET LOCK (WCP)	Bent	95.00 F	*95.00 F
7	1		*FRT GRILLE ASSY (WCP)	Cracked	165.00 F	*165.00 F
8	1		*FRT BUMPER (WCP)	Distorted	255.00 F	*255.00 F
9	1		*FRT BUMPER TOP SEAL (WCP)	Twisted	45.00 F	*45.00 F
10	1		*FRT BUMPER LOGO (WCP)	Scratched	35.00 F	*35.00 F
11	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	185.00 F	*185.00 F
12	2		*FRT BUMPER REINFORCEMENT BRACKET (WCP)	Bent	90.00 F	*90.00 F
13	2		*FRT BUMPER RETAINER (WCP)	Bent	76.00 F	*76.00 F
14	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
15	1		*FRT BUMPER LOWER GRILLE (WCP)	Torn	75.00 F	*75.00 F
16	2		*HEADLAMP (WCP)	N/s Cracked/ O/s Broken	430.00 F	*430.00 F
17	1		*HEADLAMP SUPPORT PANEL (WCP)	Bent	380.00 F	*380.00 F
18	1		*SUPPORT TOP GARNISH (WCP)	Distorted	75.00 F	*75.00 F
19	6		*TOP GARNISH CLIP (WCP)	Necessary	12.00 F	*12.00 F
20	1		*BRACE PANEL (WCP)	Bent	75.00 F	*75.00 F
21	1		*AIRCON CONDENSER (WCP)	Bent/Punctured	350.00 F	*350.00 F
22	1		*RADIATOR (WCP)	Bent/Punctured	480.00 F	*480.00 F
23	1		*RADIATOR TOP GARNISH (WCP)	Cracked	75.00 F	*75.00 F
24	1		*RADIATOR FAN COWLING (WCP)	Cracked	145.00 F	*145.00 F
25	1		*RADIATOR FAN MOTOR (WCP)	Jammed	185.00 F	*185.00 F
26	1		*RADIATOR FAN BLADE (WCP)	Bent	95.00 F	*95.00 F
27	1		*BATTERY BRACKET (WCP)	Not Necessary	45.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*AIRCON COOLING PIPE (WCP)	Not Necessary	210.00 F	*- F
29	1		*AIRCON DISCHARGE PIPE (WCP)	Not Necessary	225.00 F	*- F
30	1		*RADIATOR SPARE TANK (WCP)	Not Necessary	105.00 F	*- F
31	1		*WASHER TANK (WCP)	Not Necessary	95.00 F	*- F
32	1		*MANIFOLD (WCP)	Not Necessary	420.00 F	*- F
33	1		*FRT FENDER RH (WCP)	Buckled	180.00 F	*180.00 F
34	1		*FRT FENDER VVT-i PLATE RH (WCP)	Necessary	28.00 F	*28.00 F
35	1		*FRT FENDER INNER COWLING RH (WCP)	Torn	95.00 F	*95.00 F
36	10		*INNER COWLING CLIP (WCP)	Necessary	20.00 F	*20.00 F
37	1		*FRT BONNET SEAL (WCP)	Necessary	38.00 F	*38.00 F

F=Franchise part.

Sub Total (\$)	5,474.00	4,374.00
+ Margin on L,N Items 10.00/10.00% (\$)	547.40	437.40
Total Parts (\$)	6,021.40	4,811.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT NUMBER PLATE Bent	40.00	35.00
2	1	RADIATOR COOLANT Necessary	25.00	25.00
Sub Total (S\$)			65.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX MANIFOLD	New	120.00	0.00
4	LABOUR CHARGE	New	950.00	700.00
5	SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (S\$)			2,100.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >