



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 9215U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BADLY DENTED/ TORN	679.10	579.00
8	FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
1	N/S HEADLAMP	CRACKED	868.50	675.00
1	O/S HEADLAMP	CRACKED	868.50	675.00
1	N/S HEADLAMP TOP GARNISH CHROME	CRACKED	105.80	105.80
1	O/S HEADLAMP TOP GARNISH CHROME	CRACKED	105.80	105.80
1	FRONT GRILLE	CRACKED	511.70	511.70
1	FRONT GRILLE LOGO	CRACKED	85.00	85.00
1	BOOTLID	BADLY DENTED	824.40	554.00
1	BOOT RUBBER	TORN/DEFORMED	89.10	89.10
1	REAR END PANEL	BADLY DENTED	398.40	398.40
1	REAR END PANEL REINFORCEMENT W BRACKET	BADLY DENTED	325.50	188.00
1	BOOTLID UPPER LOCK	BENT	115.40	115.40
1	REAR BUMPER	BADLY DENTED	717.50	717.50
8	REAR BUMPER CLIPS @ \$5	NECESSARY	40.00	30.00
1	REAR BUMPER LOWER SPOILER W CHROME	BADLY DENTED	228.50	228.50
1	REAR END PANEL TOP GARNISH	BENT/WARPED	60.30	60.30
1	REAR BUMPER REFLECTOR GARNISH O/S	DENTED	50.30	50.30
1	SET REAR BUMPER REVERSE SENSOR	DENTED/JAMMED (2PCS ONLY)	501.70	298.00
	LESS 20% DISCOUNT		-	-1,099.36
			6,605.50	4,397.44
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT NO. PLATE AND GARNISH (SN)	DENTED	120.00	80.00
1	SET REAR NO. PLATE AND GARNISH (SN)	DENTED	120.00	25.00
			240.00	105.00
<u>LABOUR</u>				
	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN BOTH FRONT AND REAR CHASSIS, BOTH FRONT AND REAR FENDERS, FRONT SUPPORT PANEL AND REPLACE PARTS.		1,600.00	1,000.00

Report Ref No. CS3/ASM22012693/Rqp3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		2,000.00	1,000.00
	CHECK ELECTRICAL.		20.00	20.00
	REMOVE AND REFIT BOOTLID COMPONENTS.		150.00	50.00
	REWIRE REAR PORTION.		50.00	30.00
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	30.00
	REWIRE FRONT PORTION AND REFOCUS BOTH HEADLAMP BEAM.		100.00	30.00
	REMOVE AND REFIT LTA FRONT AND REAR NUMBER PLATE SEAL INCLUDING TRANSPORTATION.		200.00	100.00
	REMOVE AND REWIRE REVERSE CAMERA.		100.00	30.00
			4,320.00	2,290.00
GRAND TOTAL			11,165.50	6,792.44
RECOMMENDED COST OF REPAIRS				6,792.44

Report Ref No. CS3/ASM22012693/Rqp3m4-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.