

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23001817/DYA3Q2**Date:** 20/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100439432
<b>Claimant Vehicle No :</b>	SKE3302C	<b>Insured Vehicle No :</b>	SKW9712T
Date of Loss:	18/02/2023	Nature of Claim:	TP
		Claim No:	9928865088SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKE3302C</b>	Engine No:	13815020B48B20B
Make & Model:	BMW 530I, 2.0 LED NAV HUD MSPT (A)	Chassis No:	WBAJA52080WC07678
Reg. Date:	07/08/2017 (Man. Year: 2017)	Odometer:	92134 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/40 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,413.10	7,629.64	10,783.46	58.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,910.00	1,770.00	48.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,093.10</b>	<b>9,539.64</b>	<b>12,553.46</b>	<b>56.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>22,093.10</b>	<b>7,600.00</b>	<b>14,493.10</b>	<b>65.60</b>
<b>+ Car Rental (6.0 x S\$130.00/day) (S\$)</b>		780.00		
<b>Nett Liability (S\$)</b>		<b>8,380.00</b>		

**INSPECTION**

Date of Assignment:	20/02/2023	Alfred Auto Services & Supplies (HQ) Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2 Singapore 569538
Date Inspected:	20/02/2023 Inspected At:	
Estimated Period of Repair:	6.0 days	

**Adjuster:** BRYAN TANI**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT (ALUMINIUM)	Bent / Dented	2,980.00 F	*2,450.60 FN
2	1		*REAR BOOT LOGO	Necessary	199.00 F	*71.25 FN
3	1		*REAR BOOT 530I EMBLEM	Necessary	153.10 F	*66.80 FN
4	1		*REAR BOOT RUBBER	Necessary	391.00 F	*391.00 FN
5	2		*REAR BOOT LAMP	Not Necessary	798.00 F	*- FN
6	1		*REAR BOOT LOCK ASSY	Not Necessary	430.00 F	*- FN
7	1		*REAR BOOT CARPET	Not Necessary	389.00 F	*- FN
8	12		*REAR BOOT CARPET CLIPS	Not Necessary	96.00 F	*- FN
9	2		*REAR LAMP ASSY	Mtg Cracked	1,178.00 F	*1,178.00 FN
10	2		*REAR LAMP SEAL	Serviceable	180.00 F	*- FN
11	1		*REAR BUMPER SPONGE	Not fitted	330.00 F	*- FN
12	1		*REAR BUMPER (M/T)	Distorted	1,991.00 F	*1,581.90 FN
13	2		*REAR BUMPER CORNER GARNISH	Not Necessary	378.00 F	*- FN
14	2		*REAR BUMPER RETAINER	Serviceable	476.00 F	*- FN
15	1		*REAR BUMPER LOWER PAD	Distorted	531.00 F	*498.30 FN
16	2		*REAR BUMPER REFLECTOR	Not Necessary	420.00 F	*- FN
17	1		*REAR BUMPER TOWING COVER	Not Necessary	120.00 F	*- FN
18	2		*REAR BUMPER EXHAUST CHROME	Not Necessary	998.00 F	*- FN
19	2		*REAR BUMPER EXHAUST BRACKET	Not Necessary	380.00 F	*- FN
20	1		*REAR BUMPER HEAT SEAL	Serviceable	398.00 F	*- FN
21	1		*REAR BUMPER LOWER COVER	Broken	369.00 F	*196.90 FN
22	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
23	8		*REAR BUMPER REBIT	Not Necessary	80.00 F	*- FN
24	10		*SPONGE CLIPS	Not Necessary	60.00 F	*- FN
25	1		*REAR END PANEL	Repair	991.00 F	*- FN
26	1		*REAR END PANEL GARNISH	Not Necessary	391.00 F	*- FN
27	4		*REAR END PANEL CLIPS	Not Necessary	40.00 F	*- FN
28	1		*PARKING SENSOR	2PC Damaged /2PC NotNecessary	1,544.00 F	*772.00 FN
			(4 PCS)			
29	1		*PARKING SENSOR RING	2PC Necessary/2PC NotNecessary	196.00 F	*40.80 FN
			(4 PCS)			
30	1		*REAR NO PLATE & BOX	Not Necessary	150.00 F	*- FN
31	1		*FENDER CORNER GARNISH	N/S Cut / O/S Not Necessary	316.00 F	*131.80 FN
32	1		*REINFORCEMENT	Bent	990.00 F	*896.20 FN
33	1		*BUMPER CENTRE BRACKET	Cracked	390.00 F	*168.50 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	18,413.10	8,474.05
- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00	844.41
Total Parts (\$)	18,413.10	7,629.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT WIRING & CHECK	New	120.00	30.00
2	TO REMOVE & REFIT INTERIOR CARPET & GARNISH	New	180.00	100.00
3	TO KNOCKING ,STRAIGHTENING REPAIR & RENEW ALL ACCIDENT DAMAGE PARTS	New	1,400.00	800.00
4	TO RESPRAY PAINTING INNER & OUTER PARTS & ALL ACCIDENT AFFECTED AREA	New	1,600.00	800.00
5	TO DIAGNOSTIC & CHECK CONTROL UNIT ,RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,680.00</b>	<b>1,910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >