

S K AUTO CONSULTANTS

Our Reference
Vehicle No.

TP/022/0176SK
PC 5108 K

The contents of this document shall be confidential and shall not be disclosed to any third party without the prior written consent of SK Auto Consultants.

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	OUR ASSESSMENT(\$\$)
PARTS (LIST ITEMS)				
1	Rear bumper	Distored	1450.00	1450.00
1	Rear bumper reinforcement beam X ^{AA}	Distored	850.00	850.00
2	LHS & RHS rear taillamp @800 449.20	Cracked	1600.00	1600.00
1	Rear RHS door	Dented	2700.00	2700.00
1	Rear LHS door	Damaged	2900.00	2900.00
1	Rear LHS door number plate lamp assy	Damaged	230.00	230.00
1	Rear LHS door black garnish	Distored	180.00	180.00
1	Rear LHS taillamp panel	Dented	1800.00	1800.00
2	Rear LHS airduct garnish @120	Distored	240.00	240.00
1	Rear LHS airduct garnish cover	Missing	210.00	210.00
1	Rear RHS taillamp panel	Dented	1800.00	1800.00
1	Rear RHS airduct garnish cover	Distored	210.00	210.00
4	Rear RHS & LHS door hinge @80	Bented	320.00	320.00
1	Rear LHS door handle cover	Distored	160.00	160.00
2	RHS & LHS rear panel 1 @800 XR	Distored	1600.00	1600.00
2	RHS & LHS rear panel 2 @400 XR	Distored	800.00	800.00
2	RHS & LHS rear panel 3 @1800 XR	Distored	3600.00	3600.00
2	Roof top LHS & RHS inner carpet @850	Distored	1700.00	1700.00
1	Rear floor panel	Distored	1800.00	1800.00
2	RHS & LHS support beam @800	Distored	1600.00	1600.00
2	RHS & LHS rear corner inner panel @600 XR	Distored	1200.00	1200.00
1	Rear end panel	Distored	850.00	850.00
SPECIAL NETT ITEMS				
6	Rear LHS and RHS glass moulding @120.80	Necessary	720.00	720.00
1	Rear floor wooden plank	Necessary	600.00	600.00
1	60KM/H sticker	Necessary	15.00	15.00
1	Rear number plate	Bented	45.00	45.00
6	Rear LHS and RHS glass sealant @120.60	Necessary	720.00	720.00
Total Parts			27120.00	27120.00

1285

Our Reference
Vehicle No.

The contents of this document shall be confidential and shall not be disclosed to any third party without the prior written consent of SK Auto Consultants.

DISCHARGE VOUCHER

S K AUTO CONSULTANTS

Our Reference TP/022/0176SK
 Vehicle No. PC 5108 K

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts & components	8000.00	5000.00 3000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	6000.00	5000.00 2000
3	To check electrical wiring at damage areas	300.00	250.00 100
4	To remove and refix 2 door components	300.00	240.00 200
5	To remove and refix 2 door glass	300.00	240.00 200
6	To remove and refix 4 side window glass	800.00	600.00 400
7	To repair RHS chassis member beam	450.00	400.00 300
8	To perform anti rust treatment on affected areas	400.00	350.00 250
Labour Total :		16550.00	12080.00
TOTAL (PARTS & LABOUR):		43670.00	39200.00

6450

Note: (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements.

The final adjusted Lump Sum contract amount is S\$31,300/-



John Low
 Motor Surveyor

16693.56
 1285.00
6450.00
 24428.56

202
 19,542.84

Hs - \$19,550.00 / 20 days