

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23001841/HVY3M4**Date:** 24/04/2023**REFERENCE**

Insured/Claimant: HOLGER HELMUTH LINDNER Policy No: SP2003380431-01
Date of Loss: 17/02/2023 Nature of Claim: OD Claim No: 202332005432

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL8820D**
Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491030064114
Reg. Date: 02/01/2014 (Man. Year: 2013) Chassis No: WDD2043312G134038
Colour: White Odometer: 57690 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$32,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,772.80	3,311.00	2,461.80	42.64
Miscellaneous Items	85.00	60.00	25.00	29.41
Labour	1,660.00	960.00	700.00	42.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,517.80	4,331.00	3,186.80	42.39
Approved Total (Overridden) (S\$)		3,450.00		
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	7,517.80	2,450.00	5,067.80	67.41
+ GST 8.00/8.00% (S\$)	601.42	196.00	405.42	67.41
Nett Amount (S\$)	8,119.22	2,646.00	5,473.22	67.41

INSPECTION

Date of Assignment: 18/02/2023 Present Location: Wah Hong Motors & Credit Pte Ltd (HQ)
WAH HONG MOTORS & CREDIT PTE LTD
Date Inspected: 18/02/2023 Inspected At: 38 TOH GUAN ROAD EAST
#01-57 ENTERPRISE HUB
SINGAPORE 608581
Estimated Period of Repair: 4.0 days

Adjuster: Edward**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-COUPE	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL8820D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Bent	1,302.00 F	*1,302.00 F
2	1		*Bonnet logo badge (WCP)	Necessary	48.00 F	*48.00 F
3	1		*Front fender LH (WCP)	Repair	582.00 F	*- F
4	1		*Front fender shield LH (Front portion) (WCP)	Distorted	84.00 F	*84.00 F
5	1		*Front fender shield LH (Rear portion) (WCP)	Not Necessary	90.00 F	*- F
6	1		*Headlamp LH (WCP)	Broken	636.00 F	*636.00 F
7	1		*Headlamp panel LH (WCP)	Not Necessary	186.00 F	*- F
8	1		*Front bumper (WCP)	Buckled	786.00 F	*786.00 F
9	1		*Front bumper side retainer RH/LH@2*\$17 (WCP)	Necessary	34.00 F	*34.00 F
10	1		*Front bumper inner side bracket LH (WCP)	Not Necessary	60.00 F	*- F
11	1		*Fog lamp LH (WCP)	Not Necessary	342.00 F	*- F
12	1		*Fog lamp cover with outer chrome LH (WCP)	Cracked	60.00 F	*60.00 F
13	1		*Front bumper lower side chrome LH (WCP)	Cut	60.00 F	*60.00 F
14	1		*Center grille with logo badge (WCP)	Not Necessary	552.00 F	*- F
15	1		*Front reinforcement (WCP)	Not Necessary	234.00 F	*- F
16	1		*Front reinforcement side panel LH (WCP)	Not Necessary	24.00 F	*- F
17	1		*Front bumper sponge (WCP)	Not Necessary	84.00 F	*- F
18	1		*Radiator air guide RH/LH@2*\$42 (WCP)	Not Necessary	84.00 F	*- F

F=Franchise part.

Sub Total (S\$)	5,248.00	3,010.00
+ Margin on L,N Items 10.00/10.00% (S\$)	524.80	301.00
Total Parts (S\$)	5,772.80	3,311.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Center grille clips (Not Necessary)	25.00	0.00
2	1	Front bumper clips (Necessary)	35.00	35.00
3	1	Front fender shield clips LH (Necessary)	25.00	25.00
Sub Total (S\$)			85.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	800.00	400.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800.00	500.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00	60.00
Gross Labour Cost (S\$)			1,660.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >