



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2301447

INV Date 10/03/2023

Reference CS3/EQI22006425/Tqy3m4-  
'

Code EQI

### PROFESSIONAL SERVICE FEE

Vehicle No. SKP 8055A

Insured Veh. GBG 7270E

Claim No. DM22HO01086/JT

Policy No. DMCPHQ22-001085

Accident Date 04/07/2022

Inspection Date 06/07/2022

Description	Total
Survey Report	150.00
<b>Subtotal</b>	<b>150.00</b>
<b>GST (8%)</b>	<b>12.00</b>
<b>Grand Total</b>	<b>162.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**SML**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS3/EQI22006425/Tqy3m4-1 Date: 10/03/2023 Code: EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBG 7270E	Veh. Inspected	SKP 8055A
Policy No.	DMCPHQ22-001085	Coverage (\$)	0.00
Claim No.	DM22HO01086/JT	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	17/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA ODYSSEY	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JHMRC1880EC203644	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	04/07/2022	Inspection Date	06/07/2022
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 8055A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	668.64	631.20
1	REAR BUMPER L/H REFLECTOR	CRACKED	99.80	60.00
1	REAR BUMPER R/H REFLECTOR	CRACKED	99.80	60.00
1	REAR BUMPER L/H SIDE RETAINER	NECESSARY	44.40	44.40
1	REAR BUMPER R/H SIDE RETAINER	NECESSARY	44.40	44.40
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
2	REVERSE SENSOR @\$254.40	NOT WORKING	508.80	400.00
1	TAILGATE	BUCKLED	1,431.60	1,216.80
1	TAILGATE CTR "ODYSSEY" GARNISH	BROKEN	433.92	312.00
1	TAILGATE CTR LOWER CHROME	BROKEN	321.24	284.20
1	TAILGATE L/H LAMP	BROKEN	689.04	405.60
1	TAILGATE R/H LAMP	BROKEN	689.04	405.60
1	TAILGATE LOGO EMBLEM	NECESSARY	82.32	82.32
1	TAILGATE INNER LOCK	JAMMED	288.12	185.40
1	TAILGATE LOCK STRIKER	BENT	45.50	45.50
1	TAILGATE INNER HANDLE	DEFORMED	78.80	78.80
1	TAILGATE INNER TRIM BOARD	BROKEN	440.64	380.00
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	35.00	35.00
1	TAILGATE L/H HYDRAULIC STAY	BENT	476.50	253.10
1	TAILGATE R/H HYDRAULIC STAY	BENT	476.50	253.10
1	TAILGATE WEATHERSTRIP	DEFORMED	199.32	120.00
1	REAR WINDSCREEN GLASS	BROKEN	1,591.00	1,153.00
1	REAR WINDSCREEN MOULDING	NECESSARY	200.16	200.16
1	REAR WINDSCREEN WIPER ARM & BLADE	DAMAGED	192.24	192.24
1	REAR WINDSCREEN WIPER MOTOR	NOT WORKING	592.90	350.00
1	L/H TAILLAMP	SCRATCHED	454.32	454.32
1	R/H TAILLAMP	BROKEN	454.32	454.32
1	L/H TAILLAMP LOWER FILLER PANEL	TO REPAIR SEE LABOUR	221.00	-
1	R/H TAILLAMP LOWER FILLER PANEL	TO REPAIR SEE LABOUR	221.00	-

Report Ref No. CS3/EQI22006425/Tqy3m4-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT OPENING SENSOR	BROKEN	206.64	206.64
1	REAR WARNING BUZZER	BROKEN	94.50	94.50
1	REAR END PANEL - COMPLETE	BUCKLED	901.40	460.00
1	REAR END PANEL TOP GARNISH	DEFORMED	220.08	110.00
1	REAR END PANEL CTR COVER	DEFORMED	95.40	95.40
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,160.88	-
2	REAR NO. PLATE LAMP @\$52.00	NOT NECESSARY	104.00	-
1	L/H REAR FENDER INNER TRIM BOARD	NOT NECESSARY	504.95	-
1	R/H REAR FENDER INNER TRIM BOARD	DEFORMED	504.95	504.95
1	SET L/H REAR FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	35.00	-
1	SET R/H REAR FENDER INNER TRIM BOARD CLIPS	NECESSARY	35.00	35.00
	LESS 20% DISCOUNT		-	-1,928.59
			14,978.12	7,714.36
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NO. PLATE (SN)	BENT	60.00	45.00
1	SET SPARE TYRE PANEL INSULATION PAD (SN)	NECESSARY	150.00	100.00
1	ROLL REAR END PANEL SEALANT (SN)	NECESSARY	60.00	40.00
1	ROLL REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
			330.00	225.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF L/H TAILLAMP LOWER FILLER PANEL, R/H TAILLAMP LOWER FILLER PANEL AND SPARE TYRE PANEL.		2,000.00	1,200.00
	TO CHECK WIRING AND REWIRE.		60.00	50.00
	TO REMOVE AND REINSTALL TAILGATE COMPONENTS.		80.00	60.00
	TO REMOVE AND REINSTALL REAR WINDSCREEN.		150.00	120.00
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY.		120.00	80.00
	TO REMOVE AND REINSTALL REVERSE SENSOR.		140.00	50.00
	TO REMOVE AND REINSTALL REVERSE CAMERA.		150.00	50.00
	TO APPLY ANTI-RUST.		120.00	50.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		1,400.00	1,000.00
			4,220.00	2,660.00
GRAND TOTAL			19,528.12	10,599.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,500.00

Report Ref No. CS3/EQI22006425/Tqy3m4-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.