

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23001847/UJA3Q2  
**Date:** 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220065090
<b>Claimant Vehicle No :</b>	SLR6708R	<b>Insured Vehicle No :</b>	SLQ1566X
Date of Loss:	19/02/2023	Nature of Claim:	TP
		Claim No:	1875677539SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLR6708R</b>	Engine No:	PE31071472
Make & Model:	MAZDA BIANTE, 2.0 DELUXE EU6 (A)	Chassis No:	JM6CC1071H0111243
Reg. Date:	24/08/2017 (Man. Year: 2017)	Odometer:	67504 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,322.40	6,434.98	8,887.42	58.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,580.00	1,500.00	48.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,402.40</b>	<b>8,014.98</b>	<b>10,387.42</b>	<b>56.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,400.00</b>		
<b>(S\$)</b>	18,402.40	6,400.00	12,002.40	65.22
<b>+ GST 8.00/8.00% (S\$)</b>	1,472.19	512.00	960.19	65.22
<b>Nett Amount (S\$)</b>	<b>19,874.59</b>	<b>6,912.00</b>	<b>12,962.59</b>	<b>65.22</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>7,314.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,300.00</b>		

**INSPECTION**

Date of Assignment:	20/02/2023	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Date Inspected:	20/02/2023		
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,650.00 F	*1,074.30 FL
2	1		*FRONT BUMPER SIDE RETAINERS	N/S Cracked / O/SNot Necessary	130.00 F	*65.00 FL
3	1		*FRONT BUMPER FOG LAMP N/S	Holder Cracked	610.00 F	*463.70 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH N/S	Serviceable	320.00 F	*- FL
5	2		*FRONT BUMPER LOWER CHROME MOULDINGS	Necessary	700.00 F	*230.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	665.00 F	*543.20 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*FRONT FENDER N/S	Repair	1,090.00 F	*- FL
9	1		*FRONT FENDER INNER SHIELD N/S	Torn	330.00 F	*241.20 FL
10	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
11	1		*FRONT FENDER TOP REFLECTOR N/S	Broken	725.00 F	*635.52 FL
12	1		*HORN UNIT	Serviceable	108.20 F	*- FL
13	1		*DCDC-CONVERTER UNIT	Cracked	950.00 F	*650.00 FL
14	1		*HEADLAMP N/S	Cracked	3,360.00 F	*2,744.40 FL
15	1		*FRONT SUPPORT PANEL	Cracked	741.00 F	*581.20 FL
16	1		*FRONT DOOR N/S	Repair	1,021.00 F	*- FL
17	1		*BONNET	Repair	1,022.00 F	*- FL
18	1		*BONNET INNER RUBBER	Not Necessary	45.00 F	*- FL
19	1		*FRONT SPORT RIM N/S	Repair	900.00 F	*- FL
20	1		*FRONT GIRLLE	Cracked	855.20 F	*715.20 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>15,322.40</b>	<b>8,043.72</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	1,608.74
<b>Total Parts (\$)</b>	<b>15,322.40</b>	<b>6,434.98</b>

Report was unsubmitted during this print-out.
---

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	120.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO RESET & REPROGRAMME SYSTEM	New	450.00	100.00
5	TO REFILL AIR CON GAS	New	120.00	100.00
6	TO SPRAY RUST PROOFING	New	120.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	900.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,200.00	700.00
			<b>Gross Labour Cost (\$)</b>	<b>3,080.00</b>
				<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >