

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23001848/TWY3M4**Date:** 02/05/2023**REFERENCE**

Insured/Claimant:	LEE WEE LEONG	Policy No:	SP2003727012-01	
Date of Loss:	20/02/2023	Nature of Claim:	OD	Claim No: 202332005600

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR6433X		
Make & Model:	SKODA OCTAVIA, 2.0 RS TSI AIDISPLAY (A)	Engine No:	DLB032353
Reg. Date:	16/01/2020 (Man. Year: 2019)	Chassis No:	TMBBU7NE3L0045044
Colour:	Grey	Odometer:	52822 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35R19	Rear Tyre Size:	235/35R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,081.51	7,185.20	896.31	11.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,660.00	7,010.00	1,650.00	19.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,741.51	14,195.20	2,546.31	15.21
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	16,141.51	13,595.20	2,546.31	15.77
+ GST 8.00/8.00% (\$\$)	1,291.32	1,087.62	203.70	15.77
Nett Amount (\$\$)	17,432.83	14,682.82	2,750.01	15.77

INSPECTION

Date of Assignment:	20/02/2023	
Date Inspected:	21/02/2023	Inspected At: VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2023)
Parts:	143	SKODA OCTAVIA 2.0 RS TSI AIDISPLAY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR6433X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR FRT BUMPER	Deformed	1,260.00 FS	*1,260.00 FS
2	1		*GUIDE PIEC BUMPER SIDE BRACKET LH	Deformed	34.04 FS	*34.04 FS
3	1		*SENSOR BRA	Necessary	9.81 FS	*9.81 FS
4	1		*SENSOR BRA	Necessary	9.81 FS	*9.81 FS
5	1		*2K-PLASTIC ADHESIVE	Necessary	60.94 FS	*60.94 FS
6	1		*BONDING AGENT FOR PLASTIC	Necessary	53.55 FS	*53.55 FS
7	1		*COVER FOR LHS FOG LAMP GRILLE	Not Necessary	37.09 FS	*- FS
8	1		*CORNER TRI LHS FOG LAMP GRILLE SIDE TRIM	Cut	84.90 FS	*84.90 FS
9	1		*UNBEKANNT LHS H/LAMP	Cracked	1,576.14 FS	*1,576.14 FS
10	2		*BOLTHEX.HD.WITH SHOUL.	Necessary	3.80 FS	*3.80 FS
11	1		*LED FOG LA	Not Necessary	573.39 FS	*- FS
12	1		*WASH WATER RESERVOIR WIPER TANK	Deformed	105.34 FS	*105.34 FS
13	1		*PLUG	Necessary	6.63 FS	*6.63 FS
14	1		*GASKET	Necessary	1.70 FS	*1.70 FS
15	1		*WINDSHIELD CLEANER CONCEN	Necessary	16.00 FS	*16.00 FS
16	1		*FENDER	Bent	608.75 FS	*608.75 FS
17	4		*RIVETTED CAP NUT	Necessary	7.60 FS	*7.60 FS
18	1		*FENDER - B LHS FENDER BRACKET	Necessary	65.30 FS	*65.30 FS
19	1		*WHEELHOUSE LHS FENDER LINER	Cut	154.25 FS	*154.25 FS
20	1		*FOIL LHR FENDER FOIL	Cut	32.35 FS	*32.35 FS
21	1		*ALLOY WHEE LHS FRT RIM	Cut	1,176.79 FS	*1,176.79 FS
22	1		*RUBBER VALVE	Necessary	2.87 FS	*2.87 FS
23	1		*ALLOY WHEE LHS REAR RIM	Cut	1,176.79 FS	*1,176.79 FS
24	1		*RUBBER VALVE	Necessary	2.87 FS	*2.87 FS
25	1		*TAILLIGHT LHS TAILLIGHT OUTER	Cut	1,004.71 FS	*723.39 FS
26	1		*LHS FENDER TOP SPONGE	Necessary	16.09 FS	*11.58 FS
Total Parts (\$\$)					8,081.51	7,185.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	TO ALIGN LED HEADLIGHT	New	100.00	100.00
4	B&P WHEEL ALIGNMENT	New	300.00	300.00
5	R&R RIM & BALANCE	New	100.00	100.00
6	LABOUR	New	3,360.00	2,240.00
7	SPRAY PAINT	New	4,240.00	3,710.00
Gross Labour Cost (S\$)			8,660.00	7,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >