

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI23001852/UQY3E2**Date:** 06/03/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMC1625X**Insured Vehicle No :** GBH6212A

Date of Loss: 12/02/2023

Nature of Claim:

TP

Claim No: CDMCG23000351

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMC1625X**

Make & Model: VOLVO S60, 1.5 T2 (A)

Engine No: B4154T52555360

Reg. Date: 27/06/2018 (Man. Year: 2018)

Chassis No: YV1FS28L0J2468693

Colour: Grey

Odometer: 103480 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18

Rear Tyre Size:

235/45 R18

Front Left Side: Toyo 7 mm

Rear Left Side:

Toyo 7 mm

Front Right Side: Toyo 7 mm

Rear Right Side:

Toyo 7 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,166.70	5,074.20	2,092.50	29.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	800.00	760.00	48.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,726.70	5,874.20	2,852.50	32.69
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	8,726.70	4,600.00	4,126.70	47.29
+ GST 8.00/8.00% (S\$)	698.14	368.00	330.14	47.29
Nett Amount (S\$)	9,424.84	4,968.00	4,456.84	47.29

INSPECTION

Date of Assignment: 20/02/2023

Date Inspected: 22/02/2023 Inspected At:

Convergence Automotive Pte Ltd (HQ)

39 Woodlands Close, MEGA@Woodlands #01-24

Singapore 737856

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2023)
Parts:	143	VOLVO S60 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC1625X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Bent	2,480.00 FL	*2,480.00 FL
2	1		*FRONT BUMPER	Deep Cut	1,685.00 FL	*1,685.00 FL
3	1		*FRONT BUMPER SIDE RETAINER N/S	Not Necessary	145.00 FL	*- FL
4	1		*FRONT BUMPER BEAM	Not Necessary	980.00 FL	*- FL
5	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
6	1		*HEADLAMP N/S	Broken	1,473.00 FL	*1,473.00 FL
7	1		*FRONT FENDER N/S	Repair	1,150.00 FL	*- FL
					Sub Total (S\$)	7,963.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	796.30
					Total Parts (S\$)	7,166.70
						5,074.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO REFILL AIR CON GAS	New	100.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	580.00	280.00
6	TO PUTTY & SPRAY PAINTING	New	680.00	500.00
Gross Labour Cost (\$\$)			1,560.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >