



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 4346J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	130.00	130.00
1	HEAD LAMP ASSEMBLY	SCRATCHED	450.00	420.00
1	FRONT VISOR	SCRATCHED	850.00	370.00
1	FRONT V PANEL	BROKEN	130.00	130.00
1	FRONT LH SIGNAL	SCRATCHED	90.00	90.00
1	FRONT FENDER	SCRATCHED	150.00	150.00
1	FRONT SIDE PANEL LH	SCRATCHED	250.00	250.00
1	FRONT SIDE PANEL RH	SCRATCHED	250.00	250.00
1	FRONT RH SIGNAL	SCRATCHED	95.00	90.00
1	SET FORK TUBE	TO REPAIR SEE LABOUR	1,480.00	-
1	FORK UNDER BRACKET	SERVICEABLE	680.00	-
1	COMPARTMENT PANEL	SCRATCHED	330.00	330.00
1	SET BALANCER	SCRATCHED	70.00	55.00
1	BRAKE LEVER	SCRATCHED	75.00	65.00
1	MIRROR LH	SCRATCHED	60.00	60.00
1	REAR TAIL PANEL LH	SCRATCHED	190.00	190.00
1	REAR TAIL PANEL RH	SCRATCHED	190.00	190.00
1	REAR PILLION GRIP RH	SCRATCHED	150.00	136.00
1	EXHAUST GUARD	SCRATCHED	130.00	120.00
1	REAR STEP PANEL - PILLION LH	SCRATCHED	160.00	160.00
1	LOWER PANEL LH	SCRATCHED	160.00	160.00
1	SHIELD LEG LOWER	SCRATCHED	180.00	128.00
1	FRONT LH SIGNAL	NOT NECESSARY	120.00	-
1	CVT COVER	SCRATCHED	190.00	190.00
1	SHIELD LEG SIDE LH	BROKEN	210.00	128.00
	LESS 10% DISCOUNT		-677.00	-379.20
			6,093.00	3,412.80
	<u>NETT ITEMS</u>			
1	REAR CARNER BOX - KAPPA (N)	SCRATCHED	380.00	270.00
1	"200" STICKER (N)	NECESSARY	95.00	60.00

Report Ref No. CS/FCI23001856/Wqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BURGMAN EMBLEM X2 (N)	NECESSARY	250.00	120.00
			725.00	450.00
	LABOUR			
	TOWING FEES.		40.00	30.00
	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC. INCLUSIVE OF THE REPAIR OF SET FORK TUBE.		350.00	350.00
	REMOVE & REPLACE FORK TUBE/BACKET & TOP UP FORK OIL.		180.00	180.00
	RE-WRAP SEAT COVER.		120.00	60.00
	PUTTY & RESPRAY PAINT.		450.00	200.00
			1,140.00	820.00
GRAND TOTAL			7,958.00	4,682.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CS/FCI23001856/Wqy3m4

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.