



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23001856/Wqy3m4 Date: 28/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 4572J	Veh. Inspected	FBM 4346J
Policy No.		Coverage (\$)	0.00
Claim No.	D23000529MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	20/02/2023
2. Vehicle Particulars & Condition			
Make & Model	SUZUKI UH200A	c.c	200
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MLCC91327H0404004	Colour	GREY
Odometer	43386 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/90-13	CONTINENTAL	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70-12	MICHELIN	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS			
5. General Information			
Accident Date	10/02/2023	Inspection Date	21/02/2023
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	