

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23001857/DVY3E2**Date:** 15/06/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002233979
Claimant Vehicle No :	SHC3828Z	Insured Vehicle No :	SKN5858E
Date of Loss:	18/02/2023	Nature of Claim:	TP
		Claim No:	303667

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3828Z	Engine No:	G4LEKU406597
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU189380
Reg. Date:	27/02/2020 (Man. Year: 2019)	Odometer:	254488 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,930.84	9,403.32	5,527.52	37.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,480.00	2,370.00	61.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,780.84	10,883.32	7,897.52	42.05
Approved Total (Overridden) (S\$)		8,700.00		
(S\$)	18,780.84	8,700.00	10,080.84	53.68
+ GST 8.00/8.00% (S\$)	1,502.47	696.00	806.47	53.68
Nett Amount (S\$)	20,283.31	9,396.00	10,887.31	53.68

INSPECTION

Date of Assignment:	22/02/2023		
Date Inspected:	21/02/2023	Inspected At:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	5.0 days		

Adjuster: BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3828Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,253.80 FL	*- FL
2	1		*BONNET HINGE (RH)	Not Necessary	118.70 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	127.30 FL	*- FL
4	1		*RADIATOR GRILLE NEW MODEL	Cut	1,568.60 FL	*1,568.60 FL
5	1		*FRONT NUMBER PLATE GARNISH	Cut	188.00 FL	*188.00 FL
6	1		*FRONT BUMPER COVER	Torn	481.10 FL	*481.10 FL
7	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Torn	186.90 FL	*186.90 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	1,136.70 FL	*1,136.70 FL
10	1		*FRONT BUMPER REINFORCEMENT ABSORBER (RH)	Bent	186.50 FL	*186.50 FL
11	1		*FRONT BUMPER TOWING COVER	Serviceable	29.00 FL	*- FL
12	1		*FRONT BUMPER MOUDLING CENTRE UPPER	Cut	368.50 FL	*368.50 FL
13	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
14	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
15	1		*FRONT BUMPER LOWER GRILLE	Broken	365.30 FL	*365.30 FL
16	1		*FRONT BUMPER LOWER GRILLE MOULDING	Cut	127.60 FL	*127.60 FL
17	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
18	1		*FRONT BUMPER BRACKET TOP (RH)	Broken	35.00 FL	*35.00 FL
19	1		*FRONT BUMPER BRACKET (RH)	Serviceable	28.00 FL	*- FL
20	1		*FRONT BUMPER RETAINER MOUNTING (RH)	Not Necessary	65.30 FL	*- FL
21	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
22	1		*FRONT BUMPER GRILLE (RH)	Cut	186.90 FL	*186.90 FL
23	1		*FRONT BUMPER AIR DUCT (RH)	Broken	153.80 FL	*153.80 FL
24	1		*DAY LIGHT, RH	Mtg Broken	642.50 FL	*642.50 FL
25	1		*DAY LIGHT WIRE	Not Necessary	585.50 FL	*- FL
26	1		*HEADLAMP SUPPORT PANEL ASSY	Mtg Broken	1,139.30 FL	*1,139.30 FL
27	1		*HEADLAMP (RH)	Broken	3,987.30 FL	*2,110.30 FL
28	1		*RADIATOR	Bent	710.50 FL	*710.50 FL
29	1		*RADIATOR AIR GUARD (RH)	Not Necessary	76.40 FL	*- FL
30	1		*RADIATOR AIR GUARD, UPR (RH)	Not Necessary	127.50 FL	*- FL
31	1		*FRONT FENDER (RH)	Repair	490.70 FL	*- FL
32	1		*FRONT FENDER SHIELD (RH)	Not Necessary	164.70 FL	*- FL
33	1		*AIRCON CONDENSER	Bent	663.60 FL	*663.60 FL
34	1		*WIPER CONTAINER ASSY	Mtg Deformed	385.40 FL	*385.40 FL
35	1		*FRONT NUMBER PLATE }	Cracked	25.00 FS	*45.00 FS
36	1		*FRONT NO PLATE TRIM COVER }	Bent	30.00 FS	*- FS
37	1		*COOLANT	Not Necessary	45.00 FS	*- FS
38	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
39	1		*EMBLEM-BLUE DRIVE (RH)	Necessary	26.60 F	*26.60 FN
40	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	18,606.90	11,717.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,676.06	2,309.26
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	5.32
Total Parts (\$\$)	14,930.84	9,403.32

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING CHARGE	New	1,200.00	600.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	20.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX RADIATOR	New	90.00	50.00
7	REMOVE / REFIX AIRCON & REFILL GAS	New	130.00	80.00
8	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			3,850.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >