

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23001861/KYA3Q2**Date:** 18/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2004367750-01
Claimant Vehicle No :	SKW1854U	Insured Vehicle No :	SNH5016P
Date of Loss:	10/02/2023	Nature of Claim:	TP
		Claim No:	202332005316

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW1854U	Engine No:	G4FGFU404242
Make & Model:	HYUNDAI VELOSTER, 1.6 (A)	Chassis No:	KMHTC61CMGU276419
Reg. Date:	21/10/2015 (Man. Year: 2015)	Odometer:	11340 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,214.20	1,045.80	2,168.40	67.46
Miscellaneous Items	3,710.00	550.00	3,160.00	85.18
Labour	2,220.00	1,630.00	590.00	26.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,144.20	3,225.80	5,918.40	64.72
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	9,144.20	2,450.00	6,694.20	73.21
+ GST 8.00/8.00% (S\$)	731.54	196.00	535.54	73.21
Nett Amount (S\$)	9,875.74	2,646.00	7,229.74	73.21
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		57.75		
Nett Liability (S\$)		3,203.75		
Global Sum Settlement (S\$)		3,150.00		

INSPECTION

Date of Assignment:	20/02/2023 Present Location:	Accord Auto Services Pte Ltd (HQ)
Date Inspected:	21/02/2023 Inspected At:	Accord Auto Services Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts:	M1-COUPE	HYUNDAI VELOSTER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW1854U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent / Warped	550.00 F	*550.00 FL
2	1		*FRONT LH DOOR STICKER (TOP & SIDE)	Necessary	31.00 F	*31.00 FL
3	1		*REAR LH DOOR	Bent / Warped	550.00 F	*550.00 FL
4	1		*REAR LH DOOR STICKER (TOP & SIDE)	Necessary	31.00 F	*31.00 FL
5	1		*REAR LH FENDER	Repair	900.00 F	*- FL
6	1		*REAR BUMPER	Repair	800.00 F	*- FL
7	1		*REAR BUMPER SIDE RETAINER LH	Repair	60.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					2,922.00	1,162.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	116.20
+ Margin on L,N Items 10.00/0.00% (\$\$)					292.20	0.00
Total Parts (\$\$)					3,214.20	1,045.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT DOOR INNER TRIM BOARD CLIPS LH (NOT NECESSARY)	50.00	0.00
2	1	LH SIDE SKIRT COVER (REPAIR)	300.00	0.00
3	1	RE-WRAP FRONT LH DOOR HANDLE & REAR LH DOOR HANDLE (NOT NECESSARY)	120.00	0.00
4	1	RE-WRAP LH SIDE SKIRT COVER (NECESSARY)	200.00	150.00
5	1	REAR FENDER SHIELD CLIPS LH (NOT NECESSARY)	45.00	0.00
6	1	REAR BUMPER CLIPS (NOT NECESSARY)	45.00	0.00
7	1	REAR DOOR INNER TRIM BORAD CLIPS LH (NOT NECESSARY)	50.00	0.00
8	1	RIM (DENTED)	2,300.00	400.00
9	1	TYRE (SERVICEABLE)	600.00	0.00
Sub Total (\$\$)			3,710.00	550.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,200.00	1,000.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	550.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			2,220.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >