Not Northersel Ulany & Meany Afar Painy File No: Date: 00



80.00 3d

Siang Hock Car Rental Pte Ltd Blk 929 Hougang St 91 #09-131 Singapore 530929

To apply anti-corrosion Tuff-Kote

06-March-2014

Accident involving vehicle no: Description	DOMAGG	S Nissan Carava		
	PC1290S	& YP4050Z	on 13.02.2023	
Description		Quantity	Cost	Price
Front upper panel		1		
RH Headlamp outer		1		
LH Headlamp outer		. 1		
RH Headlamp inner		1		
LH Headlamp inner		1		
Front grille CRN		1		
Front grille emblem		1		
		1		
Air con blower box Air con heater box		1		
Front bumper Ru		1		
Front bumper clips (1 set) Acc	•	1		
Front bumper reforcement /X		1		
body panel alignment			\$	750.00
To remove and install dashboard and	centre console, inc	luding instrument pa	nel,	
adio, climate control module to facili	tate body repairs		\$	300.00 254
_				
To remove and check air con cooling components and vacuum and charge re				
omponents and vacuum and charge re				120.00 1001
_	efrigerant R134a a	nd check for leakage	e	120.00 1001
omponents and vacuum and charge read full functionality disconnect wire harness to facilitate	efrigerant R134a a	nd check for leakage	e	120.00 1001 50.00 201
omponents and vacuum and charge read full functionality o disconnect wire harness to facilitate connect wiring system and check for	efrigerant R134a a e repairs and check full functionality	nd check for leakage	\$ \$	
omponents and vacuum and charge read full functionality disconnect wire harness to facilitate	e repairs and check full functionality damaged portion	nd check for leakage	\$ \$ tory	

LKK Auto Consultants hence notify the Repairer of the following:

Third party survey is on a "Without Prejudice" basis

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

• To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation

No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: 1 of 1

\$

\$