



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|--|---|--|--|---------------------|-------------------------|---------------|
| LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428 | | | Ref: CS3/LIP23001870/Kvy3m4 Date: 23/02/2023 Code: LIP | | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | | |
| Insured Veh. | | PC 458H | Veh. Inspected | | PC 5829M | |
| Policy No. | | | Coverage (\$) | | 0.00 | |
| Claim No. | | BVS23/0143 | Excess (\$) | | 0.00 | |
| Assign From | | ANDY SEAH | Assign Date | | 20/02/2023 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| Make & Model | | KING LONG XMQ6 (A) | | c.c | | 6691 |
| Engine No. | | HIDDEN | | Year of Reg. | | - |
| Chassis No. | | LA6R1FSH9GB402842 | | Colour | | METALLIC GOLD |
| Odometer | | 141452 KM | | Steering | | IN ORDER |
| Brakes | | IN ORDER | | Modification | | NIL |
| General | | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | Balance | | |
| | R/H Front Tyre | 11R22.5 | FALKEN | 7 mm | | |
| | L/H Front Tyre | 11R22.5 | FALKEN | 7 mm | | |
| | R/H Rear Tyre | 11R22.5 (D) | FALKEN | 7/7 mm | | |
| | L/H Rear Tyre | 11R22.5 (D) | FALKEN | 7/7 mm | | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 15/02/2023 | | Inspect Date / Time | 20/02/2023 (11:00 AM) | |
| | Survey held at | SERVE YOU MOTOR SERVICE BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536 | | | | |
| 5a. Remarks | | | | | | |
| | A)REGISTRATION DATE: 04 MAR 2017 B)MARKET VALUE: \$63,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$30,029.00=NETT VALUE: \$32,971.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$9,000 | | | | | |
| 5b. Estimate Days of Repair | | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | | | |

Report Ref No. CS3/LIP23001870/Kvy3m4

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KL

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.