



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 3537J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (N)	BENT	720.70	636.70
2	FRONT BUMPER RETAINER (N)	O/S DISTORTED	86.80	43.40
2	FRONT BUMPER UPPER GARNISH (N)	SERVICEABLE	810.80	-
1	FRONT BUMPER ENFORCEMENT (N)	TO REPAIR SEE LABOUR	832.60	-
1	FRONT SUPPORT TOP PANEL (N)	TO REPAIR SEE LABOUR	334.40	-
1	FRONT GRILLE W CHROME (N)	SERVICEABLE	391.70	-
1	FRONT GRILLE - NISSAN LOGO (N)	NOT NECESSARY	84.90	-
2	FOGLAMP (N)	SERVICEABLE	567.60	-
2	HEALAMP (N)	O/S MTG CRACKED	1,183.40	455.00
1	FRONT BONET (N)	TO REPAIR SEE LABOUR	950.60	-
2	FRONT BONET HINGE (N)	TO REPAIR SEE LABOUR	167.20	-
	LESS 10% DISCOUNT		-613.07	-113.51
			5,517.63	1,021.59
	<u>LABOUR</u>			
	TO REMOVE DAMAGED PARTS AND ATTACHMENT REPAIR/RESHAPE DENTED AREAS REPLACE/ALIGN ALL PARTS INTO POSITION. INCLUSIVE OF THE REPAIR OF FRONT BUMPER ENFORCEMENT, FRONT SUPPORT TOP PANEL, FRONT BONET AND FRONT BONET HINGE. TO SPRAY PAINT.		800.00	300.00
			900.00	250.00
			1,700.00	550.00
GRAND TOTAL			7,217.63	1,571.59
RECOMMENDED COST OF LUMP SUM REPAIRS				1,250.00

Report Ref No. CS/LIP23001872/Kqy3m4

MARKET VALUE: \$48,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$35,178.00=NETT VALUE: \$12,822.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.