



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDM 4886T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	BADLY DENTED	1,147.47	1,147.47
2	BONNET HINGES	BENT	137.00	137.00
1	BONNET LOCK	NOT NECESSARY	185.30	-
1	HEADLAMP HID O/S	CRACKED	4,335.16	4,335.16
1	FRONT BUMPER	CUT/TORN	994.32	994.32
1	FRONT BUMPER SIDE RETAINER O/S	NECESSARY	66.50	66.50
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	392.20	-
1	FRONT BUMPER FOG LAMP GARNISH O/S	GRAZED	85.30	85.30
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	FRONT FENDERS @\$348.10	N/S TO REPAIR SEE LABOUR/ O/S DISTORTED	696.20	348.10
1	WIPER WASHER TANK	DEFORMED	182.50	182.50
	LESS 20% DISCOUNT		-1,654.39	-1,469.27
			6,617.56	5,877.08
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		80.00	60.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO RESET & REPROGRAMME SYSTEM.		180.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER(N/S).		800.00	420.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	800.00
			2,390.00	1,350.00
GRAND TOTAL			9,007.56	7,227.08

RECOMMENDED COST OF REPAIR SUM			6,500.00
---------------------------------------	--	--	-----------------

Report Ref No. CS/LPC23001876/Uqy3m4

NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.