

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/LPC 23001876/4943

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 27436

Veh No:

SDM 48867

Yr Regn:

23/11/18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

C.C

1496

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

10/786

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMBBN 22A 8K0258502

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

17/02/23

D.O.I.

17/3/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Ref.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/12

headlamp MID @ 4335.16 (MBAAR-51-0316)

NO new part replaced. Wksp went repair of
Repair sum @ 6500 (CRD @ 2507.56, 28%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

3

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.F. (\$

6500

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

Not Allowed
her
menu
17/3/23
Repair sum \$6500
4 days

VEHICLE No: SDM 4886T

1PC	BONNET	Body	\$1,147.47	—
2PCS	BONNET HINGES @\$74.60	Beif	\$137.00	—
1PC	BONNET LOCK	na	\$185.30	X
1PC	HEADLAMP HID O/S	one	\$4,335.16	—
1PC	FRONT BUMPER	cur/7.11	\$994.32	—
1PC	FRONT BUMPER SIDE RETAINER O/S	her	\$66.50	—
1PC	FRONT BUMPER REINFORCEMENT	17	\$392.20	X
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	gross	\$85.30	—
1SET	FRONT BUMPER CLIPS	den	\$50.00	—
2PCS	FRONT FENDERS @\$348.10	MSR o/s DIS	\$696.20	1/pc
1PC	WIPER WASHER TANK	Re	\$182.50	—
			\$8,271.95	
			LESS 20%	\$6,617.56

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$80.00	60
TO CONDUCT WHEEL ALIGNMENT	\$80.00	X
TO RESET & REPROGRAMME SYSTEM	\$180.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	420
TO PUTTY & SPRAY PAINTING	\$1,200.00	800
TOTAL	\$9,007.56	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-7346-35
202
5877.08
1350
7227.08
102
6504